16555A-02

S	Е	R	V	I	С	Е	Ν	0	Т	Е
							SUPERSEDE	S: None		
165	55A Deep	o Memor	y Logic	Analyz	er Modu	ule				
Ser	Serial Numbers: US34070101/US34070200									
Ma	ster/Expa	ander op	eration i	mprov	ement					
То	Be Perfor	med By:	: Agilent	-Qualif	ied Perso	onnel				
Par	ts Requi	red:								
	t No.			escripti						
165	55-66503		Ci	rcuit B	oard					
165 tior boa Sol 165 with mut	ns do not r rd multica ution/Act 55A circu h the upda	eliably op ard config ion: hit boards ated 1655 aster and 2	perate in gurations that have 5-66503 2 expand	master have b e five r board. er boar	/expande een foun master/ex The upo rds (three	er multicar Id to produ pander bo lated 1655	ive-board multic d configurations ace incorrect dat ard connectors 1 5-66503 board s ilticard configur	s. Four- a a to the u must be re supports a	eplaced a maxi-	
								C	Continued	,
							DATE: Octobe	er 1995		

ADMINISTRATIVE INFORMATION


SERVICE NOTE CLASSIFICATION:							
	MODIFICATION	RECOMMENDED					
ACTION CATEGORY:	 IMMEDIATELY ON SPECIFIED FAILURE AGREEABLE TIME 	STANDARDS: Labor 1.0 Hour					
LOCATION CATEGORY:	 CUSTOMER INSTALLABLE ON-SITE SERVICE CENTER 	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT					
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: October 1996					
AUTHOR: REB	ENTITY: 0800	ADDITIONAL INFORMATION:					

© 1995 AGILENT TECHNOLOGIES
PRINTED IN U.S.A.



Identify a suspect board by observing the number of expander board connectors on the circuit board as shown in the following figure.

If five connectors are present (J4-J8), then the board requires replacement. Order a replacement board using the 16555-66503 part number. Follow the procedures in the 16555A service manual to perform the replacement. The replacement board does not require calibration.



If only three connectors are present (J5-J7) as shown in the following figure, then the board is not to be replaced.

