3070-88

S E R V I C E N O T E

Supersedes: NONE

Agilent Medalist i3070 and i3070 Series 5 In-Circuit Test Systems

Serial Numbers:

E9901D/E/DR - All; E9902D/E/DR - All; E9903D/E/DR - All; E9905D/E/DR -All

Bios 1.12 version in rp5700 causes longer time to load board directory across network

Parts	Reg	uired:	
1 al is	ncq	un cu.	

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
MODIFICATION RECOMMENDED					
ACTION CATEGORY:	[[]] ON SPECIFIED FAILURE X AGREEABLE TIME	STANDARDS LABOR: 0.0 Hours			
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE [[]] ON-SITE [[]] SERVICE CENTER [[]] CHANNEL PARTNER	SERVICE [[]] RETURN INVENTORY: [[]] SCRAP X SEE TEXT	USED [[]] RETURN PARTS: [[]] SCRAP X SEE TEXT		
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: 1 August 2013			
[[]] Calibration Required X Calibration NOT Required		PRODUCT LINE: 80 – In Circuit Test AUTHOR: YWS			
ADDITIONAL INFORMATION: Not Applicable					

© AGILENT TECHNOLOGIES, INC. 2012 PRINTED IN U.S.A.



October 17, 2012

Rev. 20

Page 2 of 3 3070-88

Situation:

The Hewlett Packard rp5700 PC model may take a longer time to load the board directory or startup "Push Button Debug" if the board directory resides in the network server. The above symptoms occur on the rp5700 that uses **Bios version 1.12**.

How to check the Bios of the rp5700 Controller:

• Start the System Information.


Windows ® XP

Click Start -> All Programs -> Accessories -> System Tools -> System Information.

Windows ® 7

Search "System Information"

You can find the BIOS Version/Date as shown in the figure below. Please follow the steps under the Solution/Action in this service note to update to **Bios version 1.20**.



Precaution:

- No action is needed if your PC does not exhibit the above situation.
- Backup all important ICT files like bootptab, config, licenses as well as customer data if you plan to implement the recommended solution below.

Page 3 of 3 3070-88

Solution/Action:


You must perform the following steps to improve the loading time.

- 1. Update the Bios
- 2. Re-install Windows Operating System from scratch

You will not achieve the best result if any of the steps above is skipped.

Update the Bios

- Download the Bios file "SP54250.zip" at www.agilent.com/find/i3070patches
- Unzip the file and double click to extract it to C:\swsetup\SP54250 directory
- After the extraction, a webpage with the title "Bios Flash Update" will open automatically
- Click on HPQFlash to jump to "Launch HPQFlash"
- Then, click on "Launch HPQFlash"
- Follow the instructions given to update the Bios.



Re-install Windows Operating System from scratch

Reinstall the Windows operating system from scratch after completing the Bios update. Next, reinstall the ICT software. Finally, restore all the files and data that were backed up earlier.

Reactivation of Windows

In the case of some older rp5700 computers, reactivation of Windows 7 may be necessary when updating the Bios to version 1.20.

Windows is a registered trademark of Microsoft Corporation in the U.S. and other countries.