

3070-89A

Modification Recommended Service Note

Supersedes:
3070-89

Keysight i3070 Series 5 and Series 5i In-Circuit Test System

E9901E and E9901EL – All
E9902E – All
E9903E – All
E9905E and E9905EL – All
E9988E and E9988EL – All
E9986E – All

i3070 test system controller encountered intermittent testhead booting error – i3070 test system controller that uses i3070 09.10p software release may encounter testhead booting issue.

Parts Required:

P/N Description Qty.
NONE


ADMINISTRATIVE INFORMATION

ACTION	<input type="checkbox"/> ON SPECIFIED FAILURE	STANDARDS			
CATEGORY:	<input checked="" type="checkbox"/> AGREEABLE TIME	LABOR:	0.0 Hours		
LOCATION	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE	SERVICE:	<input type="checkbox"/> RETURN	USED	<input type="checkbox"/> RETURN
CATEGORY:	<input type="checkbox"/> ON-SITE (active On-site contract required)	INVENTORY:	<input type="checkbox"/> SCRAP	PARTS:	<input type="checkbox"/> SCRAP
	<input type="checkbox"/> SERVICE CENTER		<input checked="" type="checkbox"/> SEE TEXT		<input checked="" type="checkbox"/> SEE TEXT
	<input type="checkbox"/> CHANNEL PARTNERS				
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL:	May 31 2019		
	<input type="checkbox"/> Calibration Required	PRODUCT LINE:	80 – In Circuit Test		
	<input checked="" type="checkbox"/> Calibration NOT Required	AUTHOR:	Wee-Sheng, Yong		

ADDITIONAL INFORMATION:

Situation:

The i3070 Series 5 test system controller that installed i3070 software 09.10p with Windows 7 Operating System may encounter testhead boot-up issue as shown below.




The Bootp Turbo software used in 9.10p is having some conflicts with certain types of PC controller. This could happen to newly shipped systems, or existing systems upgraded from earlier software revision.

Solution/Action:


Install a newer version of BOOTP Turbo software could resolved the issue.

The correct Product version is “1.3.0.1252” and the Copyright is “Copyright@1996-2012”



Locate the following file “C:\Program Files (x86)\BOOTP Turbo\bootpt.exe”, right click mouse and select the “Properties”, then select “Details” tab as shown below:

If the Product version is “1.3” and Copyright is “Copyright@1996-2011”, it is recommended to update the BOOTP Turbo software even though the system has not experienced the boot up issue.



Download and Install Procedure:

1. Select the “New Bootpt.exe file for i3070” from www.keysight.com/find/i3070patches.

New Bootpt.exe file for i3070

The boot issue might occur due to a defect in the BOOTP Turbo software. You can install a newer version of BOOTP Turbo software to resolve the issue

[Previous Versions](#)

Driver Current Version: Control_XTPA | 2013-03-15

2. Download the “bootpt_0830.exe”
3. Backup the bootptab file at c:\Windows\system32\drivers\etc.
4. Go to “Control Panel -> Programs and Features” to uninstall BOOTP Turbo
5. To install newer version, double click on “bootpt_0830.exe”.
6. Follow the instruction to complete the installation.
7. Rename the backup bootptab in earlier step to bootptab in c:\Windows\system32\drivers\etc
8. Restart the Controller.

Revision History:

Date	Service Note Revision	Author	Reason for Change
10 May 2018	01	Wee-Sheng	As Published