

MODIFICATION RECOMMENDED

34939A-01

S E R V I C E N O T E

Supersedes: NONE

34939A - 64-Channel High Density Form-A GP Switch Module

Serial Numbers: MY44000621 – MY44000778

The relays used in these modules may have contaminated relay contacts that can cause intermittent high resistance greater than 1 ohm before the rated relay life is reached.

Parts Required:

P/N	34939-60001	Description	replacement 34939A module	Qty.	1
-----	-------------	-------------	---------------------------	------	---

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	☒ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS LABOR: 0.5 Hours	
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE ☐ ON-SITE ☒ SERVICE CENTER ☐ CHANNEL PARTNER	SERVICE INVENTORY: ☐ RETURN ☐ SCRAP ☐ SEE TEXT	USED PARTS: ☐ RETURN ☒ SCRAP ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE NO CHARGE AVAILABLE June 05, 2013		
☐ Calibration Required ☒ Calibration NOT Required		PRODUCT LINE: BL AUTHOR: TMC	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2012
PRINTED IN U.S.A.

June 11, 2012

Rev. 19



Situation:

The relays (dark blue) used in these 34939A modules may have sulfide contaminated contacts that can cause intermittent high resistance on the 64 form A channels.

Solution/Action:

If these symptoms are observed, contact Agilent Service for a replacement.