

34980A-06

Modification Recommended Service Note

Supersedes:
NONE

34980A Multifunction Switch/Measure Unit

Serial Numbers: MY56482363 - MY56484193, SG564680019 - SG56480030

The Problem – Devices found to have duplicate MAC addresses can cause an IP conflict when connected on the same local network.

Parts Required:

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

ACTION	<input type="checkbox"/> ON SPECIFIED FAILURE	STANDARDS		
CATEGORY:	<input checked="" type="checkbox"/> AGREEABLE TIME	LABOR:	0.5 Hours	
LOCATION	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE	SERVICE:	<input type="checkbox"/> RETURN	
CATEGORY:	<input type="checkbox"/> ON-SITE (active On-site contract required)	USED	<input type="checkbox"/> RETURN	
	<input type="checkbox"/> SERVICE CENTER	INVENTORY:	<input type="checkbox"/> SCRAP	
	<input type="checkbox"/> CHANNEL PARTNERS		PARTS:	<input type="checkbox"/> SCRAP
				<input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL:	31 March 2020	
	<input type="checkbox"/> Calibration Required	PRODUCT LINE:	PLGM	
	<input checked="" type="checkbox"/> Calibration NOT Required	AUTHOR:	AK	


ADDITIONAL INFORMATION:

Situation:


Media Access Control (MAC address) is a hardware address that uniquely identifies each instrument on a network. Each of the 34980A instruments must have a unique MAC address. Due to a software bug, some 34980A's have been shipped with the same MAC address [80-09-02-07-29-FF]. When 34980A's that have the same MAC address are connected to the same local area network, an IP conflict occurs.

Solution/Action:

1. Connect the 34980A instrument to a PC controller either using a GPIB cable or LAN cable.
2. Open Connection Expert to ensure a connection to the instrument is established. Take a note of the **VISA address** (GPIB or LAN address). The VISA address will be used in the 34980A MAC Address Refresh Program.vxe application as a user input.




3. Launch Keysight Interactive IO tool within Connection Expert and verify the MAC address of the instrument using SCPI command:
(a) "SYST:COMM:LAN:MAC?" : query the instrument's LAN MAC address.




4. If the MAC address is [80-09-02-07-29-FF], please proceed to step 5. Else, the instrument is not affected by the MAC address issue and no further action is required.


5. Go to URL: <ftp://ftp.keysight.com/mpusup/34980AMAC/>
6. Save 34980A MAC Address Update Refresh Program.vxe and Keysight_VEE_Runtime_9.33.exe to the PC.
7. Install Keysight VEE Runtime, if not already installed on the PC by running Keysight_VEE_Runtime_9.33.exe.
8. Open 34980A MAC Address Update Refresh Program.vxe using Keysight VEE Runtime.
9. Enter the VISA address of the instrument to be updated in the text box.



10. Click the “START” button to initiate the verification process.
11. A confirmation dialog will pop up, confirming that the instrument has the MAC address issue.



12. Click the “Continue” button to initiate the MAC address update.
13. A dialog box will pop up, indicating that the update was successful.



14. Close Keysight VEE Runtime.

Revision History:

Date	Service Note Revision	Author	Reason for Change
11 Mar 2019	01	AK	As Published