S E R V I C E N O T E

SUPERSEDES: NONE

4263B LCR Meter

Serial Numbers: JP1KD02861 / JP1KD04599

Short correction value is large by only 100kHZ on the Test Fixture

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

 P/N
 Description
 Quantity

 04263-85081
 4263B ROM Rev.01.05
 1

Situation:

This problem occurs when executing short correction for 4263B.

The short correction value does not get near to zero at the measurement parameter Ls-Q and only 100kHZ by the Test Fixture with the shorting bar (5000-4226).

When the 42091A SHORT TERMINATION is used to short, then this problem will not be noticed.

Continued

DATE: May 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: LABOR 1.0 Hours
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE RETURN USED RETURN PARTS: SCRAP SEE TEXT SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: May 2001
AUTHOR: KW	ENTITY: 3355	ADDITIONAL INFORMATION:

© 1999 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Page 2 Service Note 4263B-05

Example

The short correction value (typical) of the incorrect case and the correct case are the following.

The 4263B measurement conditions are as follows:

Measurement Parameter: Ls-Q Measurement Time Mode: LONG Test Signal Level: 1000mV Test Signal Frequency: 100kHZ Measurement Range: Auto

Connect the test fixture the 16047C or the 16047D to the 4263B UNKNOWN terminals

in order to execute short correction by the shorting bar (5000-4226).

Incorrect case correction value

- The 16047C with the shorting bar (5000-4226) is about 0.0030uH
- The 16047D with the shorting bar (5000-4226) is about 0.0180uH

Correct case correction value

- The 16047C with the shorting bar (5000-4226) is about 0.0001uH
- The 16047D with the shorting bar (5000-4226) is about 0.0001uH

Solution / Action:

Replace the ROM to revision 01.05.