4294A-04

SERVICE NOTE

Supersedes: [None]

Agilent 4294A Precision Impedance Analyzer

Serial Numbers: JP2KG00885 / JP2KG00918 (Except for JP2KG00915)

Intermittent "POWER ON TEST FAILED" Message Due to an Artwork Problem with A8 Board

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

P/N Description Qty.

04294-69508 A8 VECTOR RATIO DETECTOR 1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	[[]] IMMEDIATELY X ON SPECIFIED FAILURE X AGREEABLE TIME	STANDARDS: LABOR: 3.0 Hours	
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE X SERVICE CENTER	SERVICE [[]] RETURN INVENTORY: [[]] SCRAP [[]] SEE TEXT	USED X RETURN PARTS: [[]] SCRAP [[]] SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: MAY2003	
AUTHOR: HK ADDITIONAL INFOR	PRODUCT LINE: WN MATION:		

© AGILENT TECHNOLOGIES, INC. 2002 PRINTED IN U.S.A.



Page 2 of 2 4294A-04

Situation:

An artwork problem with the A8 board assembly intermittently causes a "POWER ON TEST FAILED" error message to occur in the power-on self test. This artwork defect dose not affect the measurement performance of the 4294A.

Solution/Action:

It is recommended that the A8 Vector Ratio Detector board assembly (P/N 04294-66508) in the 4294A (serial numbers shown above) be replaced with new one (P/N 04294-69508). Perform the required adjustments and performance tests (Refer to 4294A Service Manual).