										4352	2B-08	s-S
	S	Е	R	V	I	С	Е		Ν	0	Т	Е
	_			CO/PLL	_				SEDE	S: None	9	
	Serial Numbers: JP1KE00101 / JP2KE00624											
					WA	RNI	NG					
		A br	roken A	AC inlet ma	ay poten	ntially 1	esult in a	electric	e shoc	k hazard	l <b>.</b>	
	To Be Performed By: Agilent-Qualified Personnel											
	Parts	s Require	d:									
	Agile	ent P/N	D	escription	Qty		Memo					
	5080 0435	-4112 (*) -3270 2-00243 -1303	L R	ilicon Seal abel ear Panel use	1 1 1 1	Se Se	olution 1 olution 1 olution 2 olution 2					
	(*) S	tore in a co	ool, dry	place out o	of direct	sunligh	ıt.					
											Continue	d
							C	DATE: S	Septer	mber 200	00	
ADN	MINIST	RATIVE	INFO	RMATION	١							
SERVICE NOTE CLASSIFICATION: PRIORITY SAFETY												
ACTI CATE	ION EGORY:		IMM	EDIATEL	Y	-	NDARDS: .5 Solution #	1 or 2.0 S	olution	#2 hours I	LABOR	
			_			1		_		1		


SERVICE NOTE CLASSIFICATION:								
PRIORITY SAFETY								
ACTION CATEGORY:	IMMEDIATELY	STANDARDS: 0.5 Solution #1 or 2.0 Solution #2 hours LABOR						
LOCATION CATEGORY:	<ul><li>ON-SITE</li><li>SERVICE CENTER</li></ul>	SERVICE □ RETURN USED □ RETURN   INVENTORY: □ SCRAP PARTS: ■ SCRAP   □ SEE TEXT □ SEE TEXT						
AVAILABILITY:	ALWAYS	AGILENT RESPONSIBLE UNTIL : ALWAYS						
AUTHOR: HU	ENTITY: 3355	ADDITIONAL INFORMATION: 02G Repair Class						

© 2000 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



## Situation:

The AC inlet (P/N 1252-6951) has the potential to slip out of the instrument's rear panel slot if the AC power cord is forcefully pulled in a diagonal direction. When this happens, an exposed connection on the AC inlet module may touch the rear panel of the instrument and cause an electrical short if the AC power cord is still connected to the AC power outlet. See Figure 1.



**Figure 1 AC Inlet Connector** 

In the worst case, there is also a possibility of an electric shock hazard to the user if the user completes a circuit between the instrument panel and another grounded connection while the AC power cord is still connected to the AC power outlet.

## Solution / Action:

There are two possible solutions; one if the AC inlet is still seated in the instrument's rear panel, and a second if the AC inlet has been yanked out of the slot.

Replacement instructions in HTML format are available over the Agilent Intranet at URL

http://kobemktg.jpn.agilent.com/field\_eng/service/ (CT-PGU Kobe Service Information)

Click on "Service FAQ", click on "AC Inlet".

## Solution 1. AC Inlet Still Intact.

- Remove the AC power cable from the AC power outlet and the product.
- Remove the top, bottom, and side covers.
- Seal the hot line terminal on the AC inlet with silicon paste (P/N 5183-4112).
- Reinforce the connection between the AC inlet and the rear panel with silicon paste.
- Perform Self Test to verify instrument operation.

## Solution 2. AC Inlet Broken

- Remove the AC power cable from the AC power outlet and the product.
- Remove the top, bottom, and side covers.
- Replace the rear panel assembly with P/N 04352-00243.
- Install the new fuse P/N 2110-1303.
- Perform Self Test to verify instrument operation.




Figure 2. Repair Completed Label