								4395	A-06	5-S
S	Е	R	V	Ι	С	Е	Ν	0	Т	Е
						ę	SUPERSED	ES: None	Э	
43	4395A Network/Spectrum/Impedance Analyzer									
Po	Power Supply does not comply with CSA950/IEC950 Standards									
Se	Serial Numbers: 4395A: JP1KE00280 / JP1KE00349									
				[
				V	VARN	ING				
	POWER	R SUPPL	Y DOES N	OT C	OMPLY	WITH CSA	950/IEC950 S	STANDAI	RDS	
Τα	To Be Performed By: Agilent-Qualified Personnel									
	Parts Required:									
Pa P/I	-		Description	n	Quant	ity				
_	50-3246		Power Sup		Quant 1	ny				
			r e wer sup	P-7	1					
Sit	uation:									
CS and	The power supply board of the 4395A specified above does not comply with CSA950/IEC950 Standards. The clearance/creepage distance between the primary (CR80) and the chassis ground of the power supply do not comply with the clearance/creepage requirements of CSA950/IEC950 Standards.									
So	lution / A	ction:								
	This problem can be fixed by replacing with a new power supply. No adjustments and performance tests are required after this replacement.									
						C	ATE: Augus	st 1998		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:									
SAFETY									
ACTION CATEGORY:	 ON SPECIFIED FAILURE AGREEABLE TIME 	STANDARDS: LABOR 0.5 Hours							
LOCATION CATEGORY:	CUSTOMER INSTALLABLE	SERVICE □ RETURN USED □ RETURN INVENTORY: □ SCRAP PARTS: ■ SCRAP □ SEE TEXT □ SEE TEXT							
AVAILABILITY:	ALWAYS	AGILENT RESPONSIBLE UNTIL: ALWAYS							
AUTHOR: KW	ENTITY: 3355	ADDITIONAL INFORMATION:							

© 1998 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

