5DX-67-S

SERVICE NOTE

Supersedes: None

5DX Series I and II systems

Serial Numbers: USxxxxx101-USxxxxx248

POSSIBLE X-ray Emissions HAZARD

WARNING

X-ray radiation emission is possible on the side access panels near rivet locations.

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

Description	Qty.
KIT, RIVET REPAIR	1
Document, Kit Installation	1
Washer, Lead	6
Glazier Point	12
	KIT, RIVET REPAIR Document, Kit Installation Washer, Lead

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:				
SAFETY				
ACTION		STANDARDS:		
CATEGORY:	X ON SPECIFIED FAILURE [[]] AGREEABLE TIME	LABOR: 0.0 Hou	ırs	
LOCATION	[[]] CUSTOMER INSTALLABLE	SERVICE [[]] RETURN	USED [[]] RETURN	
CATEGORY:	X ON-SITE	INVENTORY: [[]] SCRAP	PARTS: [[]] SCRAP	
	[[]] SERVICE CENTER	[[]] SEE TEXT	[[]] SEE TEXT	
AVAILABILITY:	Lifetime of product	AGILENT RESPONSIBLE UNTIL:	Lifetime of product	
AUTHOR: JKC	PRODUCT LINE: PL80			
ADDITIONAL INFORMATION:				

© AGILENT TECHNOLOGIES, INC. 2002 PRINTED IN U.S.A.



Page 2 of 2 SN 5DX-67-S

Situation:

Lead shielding is attached to the steel frame of the access panels with two rivets and an adhesive. Over time the adhesive breaks down and the rivets alone are supporting the lead sheet. Due to system vibration, and the weight of the lead panel, the lead has been shown to deform on the rivet, which may allow x-ray emissions above the Agilent spec.

This has been fixed on newer systems by adding a lead washer behind each rivet.

Solution/Action:

CE's must carefully inspect this area of the system during the X-ray Safety Test every time it is performed. If a reading above the Agilent spec for X-ray emission is found, the system must be shut down according to the procedure in the X-ray Safety Test Report. Upon locating an emission level above the Agilent spec that appears to be coming from a rivet location on the access panels, the CE will install the parts according to the procedure and complete the X-ray Safety Test.