5DX-83A-S <u>S E R V I C E N O T E</u>

Supersedes: [5DX-83-S]

5DX Series I, II, 2L, 3 and Series 5000 Systems

Serial Numbers: All

POSSIBLE LASER EMISSION HAZARD

WARNING

Lasers are not disabled when 5DX access panels are opened

To Be Performed By: Agilent-Qualified Personnel

Parts Required:P/NDescriptionQty.N7200-84366Service Note Label1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
SAFETY		
ACTION CATEGORY: AGREEABLE TIME	STANDARDS: LABOR: 1.0 Hours	
LOCATION CATEGORY: ON-SITE	SERVICE INVENTORY: SEE TEXT	USED PARTS: SEE TEXT
AVAILABILITY: End of Support		
AUTHOR: Guy Sitler PRODUCT LINE: 80 ADDITIONAL INFORMATION: The N7200-84366 is orderable through SPD (Service Parts Delivery) at 1-800-816-8650.		
Reference the service note number in the activity description field of the SR (Service Request)		
© AGILENT TECHNOLOGIES, INC. 2005		
PRINTED IN U.S.A.	Ag	gilent Technologies

August 31, 2005

Situation:

5DX Systems with two lasers installed will not function properly if the front laser to rear laser interlock jumper cable (E7200-61706) is mis-wired. The jumper wire being mis-wired enables the lasers to stay on all the time even if an access panel interlock is opened.

Note: This situation only occurs on 5DX systems with two lasers.

Solution/Action:

- 1) Run Automatic startup.
- 2) Load the C & A Panel
- 3) From a Command prompt in the master sub-directory enter the following:

xrayoff lotest –rob23,0;ui1; gotocal – hole –laser1

Note: The stage position to view the Front Laser Spot is approximately X=15,300 Y=3,800 Z=1,500

4) Verify that the Front Laser Spot is on and visible in the Image window see Picture 1.



Picture 1

5) Open a 5DX access panel and verify that the Front Laser Spot turns off see Picture 2.



Picture 2

6) This signifies that the Front Laser did turn off and is wired properly.

- 7) If the Front Laser Spot remains on, the laser did not turn off. This means that the E7200-61706 cable is mis-wired. Continue with step 15.
- 8) Close the 5DX access panel.
- 9) Run Automatic startup.
- 10) From a Command prompt in the master sub-directory enter the following:

xrayoff lotest –rob23,0;ui1; gotocal – hole –laser2

Note: The stage position to view the Rear Laser Spot is approximately X=7,300 Y=3,800 Z=1,500

- 11) Verify that the Rear Laser Spot is on and visible in the Image window. See Picture 1.
- 12) Open a 5DX access panel and verify that the Rear Laser Spot turns off. See Picture 2.
- 13) This signifies that the Rear Laser did turn off and is wired properly. If so, continue with step 19.




Figure 1

- 14) If either Laser Spot remained on, the laser did not turn off. This means that the E7200-61706 cable is mis-wired.
- 15) Turn off the Laser Power units by turning both keys to the off position.
- 16) Reverse the LD RMT(-) and LD RMT wires on one end of the E7200-61706 cable. See Figure 1.
- 17) Turn on the Laser Power units by turning both keys to the on position.
- 18) Continue with step 1.
- 19) Close the 5DX access panel.
- 20) Run Automatic Startup.
- 21) Unload C & A Panel.

- 22) Upon completion fill out and install the Service Note label (Part Number N7200-84366) to the 5DX label area.
- Note the N7200-84366 label located to the lower right of the existing labels in the photo below.




Figure 2: N7200-84366 Service Note label installed at lower right of label area.