

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	 IMMEDIATELY ON SPECIFIED FAILURE AGREEABLE TIME 	STANDARDS: LABOR 0.5 Hours
LOCATION CATEGORY:	CUSTOMER INSTALLABLE	SERVICE □ RETURN USED □ RETURN INVENTORY: ■ SCRAP PARTS: ■ SCRAP □ SEE TEXT □ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: End of Product Support Life
AUTHOR: BM	ENTITY: 2100	ADDITIONAL INFORMATION: This is a multi Model No. Service Note

© 2001 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Situation:

The 2 phone style cables might have been improperly crimped causing intermittent connections on the cables. Could cause "Secondary Down" or "Serial Down" message.

Solution / Action:

Units returned for any reason in the specified serial number range exhibiting "Secondary" or "Serial Down" messages or intermittent communication problems. Replace the gray phone style cables.