6571A-09

<u>SERVICE NOTE</u>

Supersedes: NONE

6571A DC POWER SUPPLY, 0-8 V, 0-220 A, 1760 W. MANUALLY CONTROLLED.

Serial Numbers: A LL

The **AC INPUT SAFETY COVER** has a strain relief used to secure the AC line cord that may become loose.

Parts Required:

P/N Description Qty.

5040-1676 AC INPUT SAFETY COVER 1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	X ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 0.17 Hours (10min)	
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE [[]] ON-SITE X SERVICE CENTER [[]] CHANNEL PARTNER	SERVICE X RETURN INVENTORY: [[]] SCRAP [[]] SEE TEXT	USED X RETURN PARTS: [[]] SCRAP [[]] SEE TEXT
AVAILABILITY:	PRODUCT'S Support Life	NO CHARGE AVAILABLE UNTIL: 1/2012	
AUTHOR: CP		PRODUCT LINE: SP	
ADDITIONAL INFORMATION ONLY			

ADDITIONAL INFORMATION: <u>ONLY</u> replace the AC Safety Cover P/N 5040-1676 if the label shown in <u>Figure 8</u> does not appear on the Safety cover or if the Cover is defective due to described failure, the Safety cover should be replaced at <u>NO</u> charge to the customer.

Lost or broken AC Safety Cover will not be replaced using warranty.

© AGILENT TECHNOLOGIES, INC. 2009 PRINTED IN U.S.A.



October 9, 2009

Rev. 16 Page 1 of 4

Page 2 of 4 6571A-09

Situation:

When the incorrect nut is used or a locking Nut is put on incorrectly the strain relief will become loose.

<u>Figure 1</u> is an example of what happens when the strain relief becomes loose, the line cord becomes twisted. When a heavy line cord is used the strain relief becomes loose very easily, and the line cord can rotate freely.

<u>Figure 2</u> shows the inside of the AC Safety Cover housing the incorrect hardware is shown. It will be very difficult to tighten the strain relief. AMC (Asian Manufacturing Center) uses a special tool to tighten the locking nut. When the incorrect nut is used or a locking Nut is put on incorrectly the strain relief will become loose as described above.




Figures 3 & 5 is representative of a not without locking ribs.



Figures 4 & 6 is representative of a nut with locking ribs.

<u>Figure 5</u> <u>Figure 6</u>

Page 3 of 4 6571A-09



+Solution/Action:

The entire AC **INPUT SAFETY COVER** P/N 5040-1676 should be replaced.

RECOMMENDED WORK-AROUND

The line cord should be securely fastened at a point 6 to 12 inches away from **INPUT SAFETY COVER** as shown in **Figure 7.** When this type of strain relief is used the electrical code requires the cord/cable being held by the strain relief be secured. Doing this eliminates the cord/cable from being twisted as shown in figure 1.





The individual parts shown in <u>Figure 8</u> are not available from Agilent parts "SPO" (Support Parts Organization). It is not cost affective to repair the AC **INPUT SAFETY COVER**, a special tool is required to tighten the nut shown in Figure 2.


<u>ONLY</u> replace the AC Safety Cover P/N 5040-1676 if the label shown in Figure 8 does not appear on the Safety cover or if the Cover is defective due to described failure, the Safety cover should be replaced at <u>NO</u> charge to the customer.

Lost or broken AC Safety Cover will not be replaced using warranty.

Figure 8

Page 4 of 4 6571A-09





The information below is what is printed on the label shown in Figure 8

Required torque for securing AC Input Cover, 5040-1676, to unit is between 10 – 12 in lbs (1.13 – 1.26 N.m).

Required torque for Strain Relief screw is between tightened using 2inlb torque.

Note Other related Service Notes and affected models:

6571A-09 6671A-11 6812B-04 66000A-07

6572A-09 6672A-11 6813B-06

6573A-08 6673A-10

6574A-10 6674A-12

6575A-10 6675A-12