6575A-10

SERVICE NOTE

Supersedes: NONE

6575A DC POWER SUPPLY, 0-120V, 0-18 A, 2100 W. MANUALLY CONTROLLED.

Serial Numbers: A LL

The **AC INPUT SAFETY COVER** has a strain relief used to secure the AC line cord that may become loose.

Parts Required:

P/N Description Qty.

5040-1676 AC INPUT SAFETY COVER 1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
MODIFICATION RECOMMENDED					
ACTION CATEGORY:	X ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 0.17 Hours (10min)			
LOCATION CATEGORY:	X CUSTOMER INSTALLABLE [[]] ON-SITE X SERVICE CENTER [[]] CHANNEL PARTNER	SERVICE X RETURN INVENTORY: [[]] SCRAP [[]] SEE TEXT	USED X RETURN PARTS: [[]] SCRAP [[]] SEE TEXT		
AVAILABILITY:	PRODUCT'S Support Life	NO CHARGE AVAILABLE UNTIL: 1/2012			
AUTHOR: CP		PRODUCT LINE: SP			

ADDITIONAL INFORMATION: <u>ONLY</u> replace the AC Safety Cover P/N 5040-1676 if the label shown in <u>Figure 8</u> does not appear on the Safety cover or if the Cover is defective due to described failure, the Safety cover should be replaced at <u>NO</u> charge to the customer.

Lost or broken AC Safety Cover will not be replaced using warranty.

© AGILENT TECHNOLOGIES, INC. 2009 PRINTED IN U.S.A.



October 9, 2009

Rev. 16 Page 1 of 4

Page 2 of 4 6575A-10

Situation:

When the incorrect nut is used or a locking Nut is put on incorrectly the strain relief will become loose.

<u>Figure 1</u> is an example of what happens when the strain relief becomes loose, the line cord becomes twisted. When a heavy line cord is used the strain relief becomes loose very easily, and the line cord cable can rotate freely.

<u>Figure 2</u> shows the inside of the AC Safety Cover housing the incorrect hardware is shown. It will be very difficult to tighten the strain relief. AMC (Asian Manufacturing Center) uses a special tool to tighten the locking nut. When the incorrect nut is used or a locking Nut is put on incorrectly the strain relief will become loose as described above.





Figure 2



Figures 3 & 5 is representative of a not without locking ribs.







Figures 4 & 6 is representative of a nut with locking ribs.

Previous nut
Regal nut

Previous nut
Regal nut

Previous nut
Regal nut

Previous nut

Page 3 of 4 6575A-10

Solution/Action:

The entire AC **INPUT SAFETY COVER** P/N 5040-1676 should be replaced.

RECOMMENDED WORK-AROUND

The line cord should also be securely fastened at a point 6 to 12 inches away from **INPUT SAFETY COVER** as shown in <u>Figure 7</u>. When this type of strain relief is used the electrical code requires the cord/cable being held by the strain relief be secured. Doing this eliminates the cable or cord from being twisted as shown in figure 1.



The individual parts shown in **Figure 8** are not available from Agilent parts "SPO" (Support Parts Organization). It is not cost affective to repair the AC **INPUT SAFETY COVER**, a special tool is required to tighten the nut shown in Figure 2.

ONLY replace the AC Safety Cover P/N 5040-1676 if the label shown in Figure87 does not appear on the Safety cover or if the Cover is defective due to described failure, the Safety cover should be replaced at **NO** charge to the customer.

Lost or broken AC Safety Cover will not be replaced using warranty.

Figure 8





The information below is what is printed on the label shown in Figure 8

Required torque for securing AC Input Cover, 5040-1676, to unit is between 10 – 12 in lbs (1.13 – 1.26 N.m).

Required torque for Strain Relief screw is between tightened using 2inlb torque.

Page 4 of 4 6575A-10

NOTE Other related Service Notes and affected models:

6571A-09	6671A-11	6812B-04	66000A-07
6572A-09	6672A-11	6813B-06	
6573A-08	6673A-10		
6574A-10	6674A-12		
6575A-10	6675A-12		