66101A-07A

S E R V I C E N O T E

Supersedes: 66101A-07

66101A DC Power Module

Serial Numbers: 0000A-00000 - 3246A-00517

Leaky A2 Bias Supply Capacitors C401 & C405

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required:

P/N	Description	Qty.
0180-3587	C401	1
0180-3587	C405	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASS	SIFICATION:		
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	[[]] IMMEDIATELY X ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS: LABOR: 0.5 Hours	
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE X SERVICE CENTER	SERVICE [[]] RETURN USED [[]] RETURN INVENTORY: X SCRAP PARTS: X SCRAP [[]] SEE TEXT	
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: Product's Support Life	
AUTHOR: RJM	PRODUCT LINE: 33		
ADDITIONAL INFORMA	ATION:		

© AGILENT TECHNOLOGIES, INC. 2002 PRINTED IN U.S.A.



Page 2 of 2 66101A-07A

Situation:

There is a high probability for the A2 Bias Supply board capacitors C401 & C405 to become leaky and corrode the PCB, thus causing further damage to the A2 Bias and A1 Power PCB assemblies.

Solution/Action:

Replace Capacitors C401 and C405 "Nichicon" capacitors on the Bias Supply PC board. (C401 & C405 P/N: 0180-3587)

Visually inspect the A1 & A2 PCB areas for leakage, if leakage is evident then <u>thoroughly</u> clean the area with an appropriate PC board cleaner. Be sure to check J401 "Molex" connector on the PC board and the connector cable itself, replace the cable if it's contaminated p/n 5080-2195.

If the bias board is beyond repair then replace it with tested assembly with p/n 5060-3455.

This fix will not affect the calibration / alignment of the unit.