S E R V I C E N O T E

SUPERSEDES: NONE

6622A System DC Power Supply

Serial Numbers: See Below

Defective Cable

Duplicate Service Notes:

6621A-13	US37370560 / US37370614
6622A-11	US37360508 / US37360544
6623A-15	US37360881 / US37360939
6624A-12	US37354276 / US37354565
6625A-10	US37380297 / US37380313
6626A-10	US37370976 / US37371108
6627A-06	US37350710 / US37350765
6628A-10	US37380257 / US37380266
6629A-10	US37380484 / US37380508

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

Agilent P/N	Description	Quantity
5060-3271	CA-ASSY	1

Continued

DATE: May 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:				
MODIFICATION RECOMMENDED				
ACTION CATEGORY:	☐ IMMEDIATELY ☐ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: LABOR 0.5 Hours		
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE RETURN USED RETURN PARTS: SCRAP SEE TEXT		
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: End of Product Support Life		
AUTHOR: FJP	ENTITY: 2100	ADDITIONAL INFORMATION:		

© 2000 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Page 2 Service Note 6622A-11

Situation:

Cable that connects GPIB board and transformer, having a date code of 4/XX/2000 or any date in April of 2000, are assumed to be defective. Possible signs of failure include: unit shut down, front panel display flicker, or bus interface hang-ups. A bus interface hang-up may be indicated by a computer timeout error when the unit is in a test rack.

Solution / Action:

For units returned for any reason in the specified serial number range, replace the defective cable with a good one.