S E R V I C E N O T E

SUPERSEDES: NONE

6551A 500W General Purpose Power Supply

Serial Number: See below

Intermittent Phone Cables.

Duplicate Service Notes:

6551A-02	US36480196 / US36480220
6552A-02	US36230481 / US36230566
6553A-02	US36340231 / US36340289
6554A-02	US36340261 / US36340311
6555A-02	US36340161 / US36340171
6651A-05	US36400356 / US36400426
6652A-05	US36400331 / US36400471
6653A-05	US36400756 / US36400901
6654A-05	US36390516 / US36390746
6655A-05	US36390401 / US36390716

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

5080-2167 (Part designator W4; A2 bd. to A5 bd.) 5080-2168 (Part designator W5; A2 bd. to A1 bd.)

Continued

DATE: August 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: LABOR 0.5 Hours	
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE RETURN USED RETURN PARTS: SCRAP SEE TEXT SEE TEXT SEE TEXT	
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: End of Product Support Life	
AUTHOR: BM	ENTITY: 2100	ADDITIONAL INFORMATION: This is a multi Model No.	

© 1999 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Page 2 Service Note 6651A-05

Situation:

The 2 phone style cables might have been improperly crimped causing intermittent connections on the cables. Could cause "Secondary Down" or "Serial Down" message.

Solution / Action:

Units returned for any reason in the specified serial number range exhibiting "Secondary" or "Serial Down" messages or intermittent communication problems. Replace the gray phone style cables.