S E R V I C E N O T E

SUPERSEDES: NONE

70100A Power Meter

Serial Numbers: 0000U00000 / 3603U00674

Modification to Eliminate Loose Reference Oscillator N-type connectors

To Be Performed By: Agilent-Qualified Personnel

Recommended Installation:

On customer reported loose Reference Oscillator connector.

Parts Required:

P/N	Description	Quantity
3050-1916	Spring Washer	1
E4418-00015	Lock Washer	1
2950-0132	Nut	1

Continued

DATE: January 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFI	CATION:		
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	☐ IMMEDIATELY☐ ON SPECIFIED FAILURE☐ AGREEABLE TIME	STANDARDS: LABOR 1.0 Hours	
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE ☐ ON-SITE ☐ SERVICE CENTER	SERVICE RETURN USED RETURN PARTS: SCRAP SEE TEXT	
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: January 1999	
AUTHOR: PN	ENTITY: E600	ADDITIONAL INFORMATION:	

© 1997 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Page 2 Service Note 70100A-01

Situation:

Multiple connections of power sensors to the Reference Oscillator, together with the weight of the sensor, have been causing lateral movement on the connector which has distorted the mounting hole on the front panel. This has in turn allowed the retaining nut to rotate backwards and make the connector even looser. Tightening the nut has fixed the problem in the past but the problem has re-occured in some instances because the front panel hole distortion still exists.

Solution/Action:

A new fixing mechanism has been introduced which includes a spring washer and a lock washer. If the hole distortion occurs these two washers ensure that the nut remains under tension and cannot rotate. The connector therefore does not come loose. The instrument will need to be stripped down to give access to the rear of the Reference Oscillator connector on the front or rear panel. See Figure 1. for instructions on how to put on the new fixing hardware.




Figure 1