S E R V I C E N O T E

SUPERSEDES: None

70908A RF Section

Serial Numbers: 0000A00000 / 9999A99999

Multiplier Power Out Adjustment

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required: Module Verification Software part number 70908-10008

(Revision B.02.00)

Situation:

To help reduce SYTFMD (5086-7741) discriminator unlock errors the adjustment software for the LO Multiplier (5086-7742) is being modified. If the Multiplier is capable of producing more power, than the software will allow 1 dB more of output power in the 4L-Band (12.6 GHz to 22 GHz).

Continued

DATE: January 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY☐ ON SPECIFIED FAILURE☐ AGREEABLE TIME	STANDARDS: Labor 1.0 Hour
LOCATION CATEGORY:	■ CUSTOMER INSTALLABLE■ ON-SITE■ SERVICE CENTER	SERVICE ☐ RETURN USED ☐ RETURN INVENTORY: ☐ SCRAP PARTS: ☐ SCRAP SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: Product's Support Life
AUTHOR: RDS	ENTITY: 5340	ADDITIONAL INFORMATION:

© 1996 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Solution/Action:

Implement the following steps to modify the software:

Insert the Adjs Disk into your computer's default drive.

- 1. LOAD "MULT_PWR"
- 2. ENTER or RETURN
- 3. REN 1,1
- 4. ENTER or RETURN
- 5. EDIT 492
- 6. ENTER or RETURN
- 7. Change line 492 to read:

Min range=MIN(Meas pwr-Power delta(Band num), 13.25)-(2*Toler(2))

- 8. ENTER or RETURN
- 9. Change line 493 to read:

Min_range=MIN(Meas_pwr-Power_delta(Band_num), 13.25)+Toler(2)

- 10. ENTER or RETURN
- 11. PURGE "MULT_PWR"
- 12. ENTER or RETURN
- 13. STORE "MULT_PWR"

Note

The write/protect switch on the disk needs to be in the write mode.

14. ENTER or RETURN