

MODIFICATION RECOMMENDED –
CORRECTS MANUFACTURING OR DESIGN DEFECTS

81110A-05B

S E R V I C E N O T E

Supersedes:
81110A-05A

81100 Family Pulse Pattern Generators

Serial Numbers: DE41B03046 / DE41B04484

All serial numbers < DE41B04484 when a new display is installed

**Intermittent display failures
(shifting lines, inverted, fully lit or completely dark display)**

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

P/N	Description	Qty.
0960-0996	Filter Plate	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR: 0.25 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	USED PARTS:	<input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AUTHOR: SM	PRODUCT LINE: 24	AGILENT RESPONSIBLE UNTIL:	May 2007
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2005
PRINTED IN U.S.A.



May 9, 2005

Situation:


Intermittently the front panel display may show shifting lines that are falling back to their normal state. Additionally an inverted display, a display with all pixels lighted or a blank display may occur intermittently.

After cycling the power of the pulse generator the display works normally again. Reproducing the symptom might not be possible.

Solution/Action:

The following rework will improve the behavior of the display:

- Remove the front frame and unplug the connector cable from the 81100 mainframe.
- Carefully remove the display module from the front frame and check for a capacitor that might have been added during an earlier intermittent modification (see picture below). If there is such a capacitor, unsolder it from the module. Re-install the display into the front frame.



- On the 81100 mainframe replace the existing filter plate with the new filter plate, p/n 0960-0996. The new filter plate can be identified by a single connector pin that shows a red color code.

