

8481A-01

S E R V I C E N O T E

Supersedes:
None

8481A - Power Sensor, 10 MHz to 18 GHz, -30 to +20 dBm

Serial Numbers: ALL

Prevention of Bulkhead Lead Wire Breakage

Parts Required:

P/N	Description	Qty.
-----	-------------	------

None

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:	
INFORMATION ONLY	
AUTHOR: WPC	PRODUCT LINE: WC
ADDITIONAL INFORMATION:	

© AGILENT TECHNOLOGIES, INC. 2010
PRINTED IN U.S.A.

February 1, 2010

Rev. 17



Agilent Technologies


Situation:

Bulkhead lead wire breakage is due to inappropriate straightening method.

Solution/Action:

Recommended procedure for preventing the bulkhead lead wire from breaking:

1. Remove the bulkhead cap by a straight pull to the right as shown in the following figure. This is to prevent the bending of the wire.



2. If the wire is bent after removing the cap, use tweezers to straighten the bent wire as shown in the following figure



Note: Do not use your fingers to straighten the wire.