

8481A-10

Modification Recommended Service Note

Supersedes: NONE

8481A- Power Sensor, 10 MHz to 18 GHz, -30 to +20 dBm

Serial Numbers: "MY54460003, MY55050001, MY55050002, MY55260003, MY55260004, MY55410002, MY55410003, MY56060002, MY56060003, MY56060004, MY56120002, MY56120003, SG55260003, SG55260004"

The Problem:

In the Measurement report of 8481A, the Reference Calibration factor at 50MHz stated is inconsistent with the 50MHz Calibration Factor listed in the table.

Parts Required:

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[[x]] ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 1 Hours		
LOCATION CATEGORY:	[]] CUSTOMER INSTALLABLE []] ON-SITE (active On-site contract required) [[x]] SERVICE CENTER []] CHANNEL PARTNERS	SERVICE: [[]] RETURN USED [[]] RETURN INVENTORY: [[]] SCRAP PARTS: [[]] SCRAP [[X]] SEE TEXT [[X]] SEE TEXT		
AVAILABILITY	: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 01-Nov-2017		
	[[X]] Calibration Required [[]] Calibration NOT Required	PRODUCT LINE: WN AUTHOR: LSL		

ADDITIONAL INFORMATION:

Service Inventory and Used part is Not Applicable.



Situation:

An inconsistency was discovered on the measurement report of 8481A. The Reference Calibration Factor at 50MHz is inconsistent with 50MHz Calibration Factor listed in Table 1 below.

This may cause a measurement error of up to 3% when user enters the Cal Factor into the system.

Ref	erence	Calibration F	<u>actor, at 50</u>	MHz = 100.0%
FREQUENCY		CALIBRATION	REFLECTION	REFLECTION
MHz		FACTOR %	LIN MAG	PHASE DEG
		00 dBm		
	10.0	98.9	0.051	-94.8
	30.0	99.1	0.022	-122.2
	50.0	99.2	0.017	-141.2
	100.0	99.7	0.014	-168.0
	300.0	99.3	0.013	139.9
	500.0	98.9	0.013	101.5
1000.		98.8	0.016	24.4
	1500.0	98.7	0.017	-27.0
	2000.0	98.4	0.018	-93.4
	3000.0	97.7	0.021	126.2
	4000.0	97.4	0.031	14.8
	5000.0	97.1	0.026	-88.9
	6000.0	96.8	0.015	143.6
	7000.0	96.5	0.014	-20.5
	8000.0	96.0	0.016	-169.6
	9000.0	95.6	0.029	55.2

Table 1: Report on Calibration Factor

Solution/Action:

This issue can be fixed by re-calibrating the affected unit. New CoC (Certificate of Calibration) and measurement report will be regenerated.

Please contact Keysight Technologies' Customer Contact Center at <u>www.keysight.com/find/contactus</u> for the recommended product modification.

Revision History:

Date	Service Note Revision	Author	Reason for Change	
21 October 2016	01	LSL	As Published	
21 October 2016	01	LSL	As Published	