# S E R V I C E N O T E

SUPERSEDES: 8495D-01

# 8495D Manual 11DB Attenuator

08494-60009 Replacement Assembly-8494B-001 08494-60012 Replacement Assembly 8494B-002 08494-60013 Replacement Assembly 8494B-003 08495-60029 Replacement Assembly 8495D-004 08495-60030 Replacement Assembly 8495B-001 08496-60016 Replacement Assembly-8496B-001 08496-60017 Replacement Assembly-8496B-002 08496-60020 Replacement Assembly 8496A-002

# Step attenuator knob modification

# **Serial Numbers:**

Specific serial number affected, likely to be affected, but not restricted to:

# Product / serial number (Japan affected units):

#### 8494A

MY41110101 MY41110110 MY41110116 MY41110118 MY41110120 MY41110122 MY41110123 MY41110124 MY41110126 MY41110128 MY41110129 MY41110130 MY41110143 MY41110144 MY41110145 MY41110146 MY41110147 MY41110148 MY41110149 MY41110151 MY41110162 MY41110165 MY41110167 MY41110168

Continued

DATE: July 2001

# ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	<ul><li>■ IMMEDIATELY</li><li>□ ON SPECIFIED FAILURE</li><li>□ AGREEABLE TIME</li></ul>	STANDARDS: LABOR 0.5 Hours
LOCATION CATEGORY:	<ul><li>■ CUSTOMER INSTALLABLE</li><li>□ ON-SITE</li><li>■ SERVICE CENTER</li></ul>	SERVICE RETURN USED RETURN PARTS: SCRAP SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: July 2003
AUTHOR: RK	ENTITY: 5534	ADDITIONAL INFORMATION:

© 2001 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Page 2 Service Note 8495D-01A

## 8494B

MY41110124 MY41110126 MY41110129 MY41110130 MY41110134 MY01110136 MY41110150 MY41110151 MY41110152 MY41110153 MY41110156 MY41110159 MY41110162 MY41110163 MY41110164 MY41110165 MY41110166 MY41110183 MY41110184 MY41110189

#### 8495A

MY41110104 MY41110119 MY41110120

#### 8495B

MY41110116 MY41110118 MY41110117 MY41110119 MY01110115 MY41110142 MY41110143 MY41110141 MY41110114 MY41110113 MY41110138

## 8496A

MY41110101 MY41110102 MY41110116 MY41110117 MY41110120 MY41110121 MY41110122 MY41110123 MY41110124 MY41110125 MY41110126 MY41110127 MY41110128 MY41110129 MY41110130 MY41110151 MY41110152 MY41110153 MY41110157 MY41110159 MY41110160 MY41110161

**Duplicate Service Notes:** 8494A-01 8494B-01

8495A-01 8495B-01 8495D-01 8496A-01

8496B-01

To be Performed By: Agilent Service Center or customer

### **Situation:**

**Loose Knob:** Manual attenuator knob rotates on shaft without actuating the attenuation steps. **Tight Knob:** Manual attenuator knob, while rotating, drags against the housing.

This seems to be an isolated incident that could occur with all manual attenuators. Checks have been put in place and design changes are in the works to minimize chance of problem occurring in the future.

# **Solution / Action:**

Suggested Fix For Loose Knob:

- 1. Tighten set screw to 50 oz-in
- 2. Rotate knob clockwise until it hits the stop
- 3. Loosen set screw
- 4. Push knob against attenuator and pull back just off of surface so knob will not rub while turning.
- 5. Align '0' in the window
- 6. Tighten set screw to 50 oz-in. CAUTION, watch for hex head stripping out in set screw while tightening.

Continued

Service Note 8495D-01A Page 3

## 7. What to look for:

Rotate knob counter clockwise through all steps without knob slipping on shaft. Knob rotation should be accompanied by clicking as actuation of the attenuation steps occurs. If rotation occurs without clicking this indicates knob is not holding shaft firmly.

- During rotation the knob should not rub against the attenuator causing excess friction or drag during rotation (see step 4).
- Attenuation numbers clearly appear in the window during each attenuation step.

Suggested Fix for Tight Knob:

- 1. Rotate knob clockwise until it hits the stop.
- 2. Loosen set screw.
- 3. Push knob against attenuator and pull back just off of surface so knob will not rub while turning.
- 4. Align '0' in the window.
- 5. Tighten set screw to 50 oz-in. CAUTION, Watch for hex head stripping out in set screw while tightening).

## 6. What to look for:

- Rotate knob counter clockwise through all steps without knob slipping on shaft. Knob rotation should be accompanied by clicking as actuation of the attenuation steps occurs. If rotation occurs without clicking this indicates knob is not holding shaft firmly.
- During rotation the knob should not rub against the attenuator causing excess friction or drag during rotation (see step 4).
- Attenuation numbers clearly appear in the window during each attenuation step.