# S E R V I C E N O T E

SUPERSEDES: None

## 85110L Test Set

**Serial Numbers:** 0000A00000 / 3235A00110

## D.C. Return Upgrade Kit

To Be Performed By: Agilent-Qualified Personnel

## **Duplicate Service Notes:**

85110A-01

8514A-04

8517A-01

8514B-01

8517B-01

8515A-04

85110L-01

#### Parts Required:

Part No. Description

08510-60121 D.C. Return Upgrade Kit

Continued

DATE: October 1995

## **ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: Labor 1.0 Hour
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: Product's Support Life
AUTHOR: JB	ENTITY: 5340	ADDITIONAL INFORMATION:

© 1995 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



#### **Situation:**

The 8514A/B, 8515A, 8517A/B & 85110A/L test set switch splitter/switch driver generates a pulse each time the switch splitter switches between port 1 and port 2. These pulses get capacitively coupled through the switch splitter and into the 8360 series source. The source ALC loop reacts to the pulses so that the 8360 generates an overmodulation error which gets reported to the 8510C when using the power domain feature included with 8510C rev C.07.00 firmware or greater.

#### **Solution/Action:**

The overmodulation error can be eliminated by installing the D.C. return upgrade kit part number 08510-60121. The kit contains the necessary parts and instructions to eliminate this possible overmodulation error. This kit is only necessary in systems with the following sources:

 Source:
 Serial Prefix

 83620/22/30/50
 3245A/9999A

 83621/31/51
 3139A/9999A