8517B-01

S	Е	R	V	Ι	С	Е	Ν	0	Т	E
							SUPERSED	ES: None)	
851′	7B Tes	st Set								
Seria	ıl Numb	ers: 000	0A00000) / 3346.	A00245					
D.C.	Retur	n Upgr	ade Ki	t						
To B	e Perfor	rmed By:	Agilent	-Qualifi	ed Person	nnel				
		ervice No	tes:							
85110A-01										
8514A-04 8517A-01										
8517 8514										
8517										
8515										
	0L-01									
Parts	s Requir	red:								
Part				escripti						
0851	0-60118		D	.C. Retu	ırn Upgra	de Kit				
								C	Continued	!

DATE: October 1995

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:								
MODIFICATION RECOMMENDED								
ACTION CATEGORY:	 ☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME 	STANDARDS: Labor 1.0 Hour						
LOCATION CATEGORY:	CUSTOMER INSTALLABLE	SERVICE I RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT						
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: Product's Support Life						
AUTHOR: JB	ENTITY: 5340	ADDITIONAL INFORMATION:						

© 1995 AGILENT TECHNOLOGIES
PRINTED IN U.S.A.



Situation:

The 8514A/B, 8515A, 8517A/B & 85110A/L test set switch splitter/switch driver generates a pulse each time the switch splitter switches between port 1 and port 2. These pulses get capacitively coupled through the switch splitter and into the 8360 series source. The source ALC loop reacts to the pulses so that the 8360 generates an overmodulation error which gets reported to the 8510C when using the power domain feature included with 8510C rev C.07.00 firmware or greater.

Solution/Action:

The overmodulation error can be eliminated by installing the D.C. return upgrade kit part number 08510-60118. The kit contains the necessary parts and instructions to eliminate this possible overmodulation error. This upgrade is only necessary in systems with the following sources:

Source:	Serial Prefix
83620/22/30/50	3245A/9999A
8321/31/51	3139A/9999A