						856	3E-2	24A
S E	R V	I	С	Е	Ν	0	Т	Ε
				SL	JPERSEDE	S: 8560I	E-24	
8563E Por	·table Spectru	m Aı	nalyzer					
	ers: See below		J					
Possible F	ailure of A6A1	High	Voltag	e Module				
Duplicate Ser	rvice Notes:	•	-					
8560E-24A	Serial Numbers	374	5A03321	/3825A0374	6			
8561E-20A	Serial Numbers			/3821A0234				
8562E-12A	Serial Numbers	374	5A00600	/3821A0098	5			
8563E-24A	Serial Numbers	374	5A08190	/3821A0954	4			
8564E-19A	Serial Numbers	374	5A01065	/3835A0135	4			
8565E-19A	Serial Numbers	374	5A00837	/3835A0100	9			
To Be Perfor	med By: Agilent-	Qualif	ied Perso	nnel, Custon	ner			
Parts Requir	red:							
P/N	Descriptio	n						
5062-7089	A6A1Hig	h Volt	tage Modi	ıle				
08564-69031	U		C	so be require	ed.			
		11		ł				
							Continue	ed

DATE: March 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:								
MODIFICATION RECOMMENDED								
ACTION CATEGORY:	 IMMEDIATELY ON SPECIFIED FAILURE AGREEABLE TIME 	STANDARDS: LABOR 0.5 Hours						
LOCATION CATEGORY:	CUSTOMER INSTALLABLE	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT SEE TEXT						
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: March 2001						
AUTHOR: GPB	ENTITY: 5320	ADDITIONAL INFORMATION:						

© 1999 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Situation:

An internal design characteristic in the High Voltage module can cause internal arcing and result in a field failure. The failure is manifested by a blank display.

Solution:

Newer High Voltage Modules have been redesigned to help prevent this failure. Instruments being serviced for blank displays should have the A6A1 replaced, even if the display failure is caused by another assembly. Remember to perform the 110 Volt adjustment. In addition, if damage due to arcing is visible on the A6 Power Supply assembly under where the A6A1 mounts, A6 as well.