# S E R V I C E N O T E

SUPERSEDES: None

# 85942A Video Signal Monitor

**Serial Numbers:** 0000U00000 / 3512U00160

## **Line Module Wire-Routing Modification**

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

**Part No.** Description 1400-0249 Tie-wrap (x2)

#### **Situation:**

These instruments have two wires that come out of the power supply line module and go to the power supply assembly. With the current routing, these wires pass close to capacitor C25 on the power supply assembly. The wires are properly insulated, however, a break in the insulation could conceivably result in a safety problem. This a a MINIMAL risk, but is actioned as a result of a CSA approval requirement.

Note that most of the above serial numbers will be modified at the division (QMD), as part of a separate upgrade process, and will therefore not require attention.

Continued

DATE: January 1996

#### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
SAFETY		
ACTION CATEGORY:	<ul><li>■ ON SPECIFIED FAILURE</li><li>□ AGREEABLE TIME</li></ul>	STANDARDS: Labor .5 Hour
LOCATION CATEGORY:	■ CUSTOMER INSTALLABLE □ ON-SITE ■ SERVICE CENTER	SERVICE
AVAILABILITY:	ALWAYS	AGILENT RESPONSIBLE UNTIL: ALWAYS
AUTHOR: DC	ENTITY: E600	ADDITIONAL INFORMATION:

© 1996 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



### **Solution/Action:**

The wires can be tied back, so that adequate separation between the wires and C25 is maintained. Add one tie-wrap (1400-0249) to the BLUE wire, and one tie-wrap to the BROWN wire. Attach to each wire, as shown in Figure 1.




Figure 1