# SERVICE NOTE

Supersedes: NONE

85963A-1201

## 85963A Instability in Sweep

Serial Numbers: Only as needed. To be performed when a variation at low end of spectrum is observed. The variation is more dramatic between 5 and 15 mhz. In most cases the deviation is between 1 and 2 db, extreme cases would exhibit themselves at 3 db and above. Perform this change only if the variation is observed.

# Noise at low end of sweep caused by impedence change of ALC circuit that controls source output during blanking.

To Be Performed By: Agilent-Qualified Personnel Only

Parts Required:			
P/N: 0160-7751	Description	CS CE.010U 50B	Qty. 2

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:							
MODIFICATION RECOMMENDED							
ACTION CATEGORY:	[]] IMMEDIATELY []] ON SPECIFIED FAILURE []] AGREEABLE TIME	STANDARDS	S: LABOR: 0.0 Hou	ırs			
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE [[]] SERVICE CENTER	SERVICE INVENTORY:	[[]] RETURN [[]] SCRAP [[]] SEE TEXT	USED PARTS:	[[]] RETURN [[]] SCRAP [[]] SEE TEXT		
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESP	PONSIBLE UNTIL:	•			
AUTHOR: [initials]	PRODUCT LINE: [product line]						
ADDITIONAL INFORMATION:							
© AGILENT TECHN	OLOGIES, INC. 2001						

PRINTED IN U.S.A.



January 11, 2002

#### Situation:

Noise at low end of sweep caused by impedance change of ALC circuit that controls source output during blanking.

#### Solution/Action:

Add two 0.01 microFarad capacitors (0160-7751) to RF Module #85961-63035-1 at the following locations: One in parallel with C114 (470pF) capacitor (new R/D C222) and one in parallel with C128 (new R/D C223)

Documents Affected 85961-60035-1 from revision M to N 85961-60035-2 from revision B to C

See PCO 65406 for more information