S E R V I C E N O T E

SUPERSEDES: None

87421A Power Supply

Serial Numbers: 3116A00101 / 3116A00150

A potential shock hazard is present if the rivets fastening the AC power input module cause the plastic case to fracture.

To Be Performed By: Agilent Service Facility

Parts Required: Replace power supply; order new 87421A.

Situation:

The power input module is secured to the plastic case of the power supply by two metal rivets. If improperly installed, these rivets can cause the plastic case to fracture. Should this occur, the power input module may pull out of the housing, exposing a potential shock hazard.

Solution/Action:

Agilent will replace any unit that has metal rivets. Should the housing be found to be broken, remove the AC (mains) power to the power supply at the AC supply outlet.

Continued

DATE: 21 February 1992

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
SAFETY		
ACTION	ON SPECIFIED FAILURE	STANDARDS:
CATEGORY:	AGREEABLE TIME	Labor 0.5 Hours
LOCATION	☐ CUSTOMER INSTALLABLE	SERVICE RETURN USED RETURN
CATEGORY:	ON-SITE	INVENTORY: SCRAP PARTS: SCRAP
	SERVICE CENTER	☐ SEE TEXT ☐ SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBILE UNTIL: ALWAYS
AUTHOR: LL	ENTITY: 4500	ADDITIONAL INFORMATION:

© 1992 AGILENT TECHNOLOGIES PRINTED IN U.S.A.





DO NOT REMOVE THE POWER CORD FROM THE POWER SUPPLY WHILE STILL PLUGGED INTO THE MAINS.

Return the power supply to the nearest Agilent sales and service office. The power supply will be exchanged for one with black nylon fasteners securing the AC input module.

All units with serial number 3116A00151 and above use black nylon fasteners to secure the AC input module. This service note does not apply to units with black nylon fasteners or with serial number 3116A00151 and above.