Modification Recommended Service Note

Supersedes: NONE

AE6943A MATEnet to SMA Automotive Adapter

Serial Numbers: WT16539 to WT23282 Manufacturing ID Number: 1101171000

The Problem -Potential characteristic impedance differential mode (CIDM) measurement failure on AE6943A

Parts Required:

P/N Description Qty.

AE6943A-FG SMA to MATEnet Automotive Adapter x1 AE6943-66600 SMA to MATEnet Adapter PCA x1

ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[X] ON SPECIFIED FAILURE [X] AGREEABLE TIME	STANDARDS LAI	BOR: 1.0 Hours			
LOCATION CATEGORY:	[X] SERVICE CENTER [[]] ON-SITE (active On-site contract required) [[]] CHANNEL PARTNERS	SERVICE: INVENTORY:	[[]] RETURN [[]] SCRAP [X] SEE TEXT	USED PARTS:	[X] RETURN [[]] SCRAP [[]] SEE TEXT	
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: 30 Jun 2024				
	[[]] Calibration Required [X] Calibration NOT Required	PRODUCT L AUTHOR: N				

ADDITIONAL INFORMATION:



Situation:

We have identified a known impedance issue with the AE6943A. The characteristic impedance differential mode (CIDM) measurement of AE6943A is not meeting requirement of 100 Ω ± 5 % at a rise time of 50 ps.

This will affect performance requirements of the link test measurements that use the AE6943A, like insertion loss (IL), return loss (RL), etc.

Reference document:

Open Alliance TC9 UTP 2.0 Channel and Components 2.0 Requirements for 1000BASE-T1 Link Segment Type A.

Solution/Action:

Contact customer service center for help to validate if there is impedance failure in AE6943A adapter. If yes, Keysight will proceed to send a fresh unit for replacement. Warranty remains no change.

Revision History:

Date	Service Note Revision	Author	Reason for Change	
13 Jul 2023	01	MC.Lim	As Published	