B1500A-05

# SERVICE NOTE

Supersedes: NONE

# B1500A Semiconductor Device Analyzer

Serial Numbers: JP10N00101/JP40N00615 (B1500A Mainframe)

JP10N00901/JP10N00911 (B1517A HRSMU module for B1500A) JP10N00101/JP20M00429 (B1511A MPSMU module for B1500A)

## Unexpected noise output from HRSMU/MPSUM on specified condition

**Parts Required:** 

P/NDescriptionQty.B1517-61011HRSMU moduleup to 10B1511-61011MPSMU moduleup to 10

To be performed by Agilent-Qualified personnel.

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION RECOMMENDED			
ACTION CATEGORY:	[X] ON SPECIFIED FAILURE [] AGREEABLE TIME	STANDARDS  LABOR: 2.0 Hours	
LOCATION CATEGORY:	[] CUSTOMER INSTALLABLE [] ON-SITE [X] SERVICE CENTER [] CHANNEL PARTNER	SERVICE [] RETURN INVENTORY: [X] SCRAP [] SEE TEXT	USED [] RETURN PARTS: [X] SCRAP [] SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: 31st Oct. 2010	
AUTHOR: JI		PRODUCT LINE: PL1H	
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2009 PRINTED IN U.S.A.



March 30, 2009

Rev. 16

Page 2 of 2 B1500A-05

#### **Situation:**

The B1500A within the listed serial number range may have the problem that the installed MPSMU/HRSMU modules generate unexpected noise.

#### **Solution/Action:**

#### FE/AE:

Involve the AE (Application Engineer) to confirm if customer's SMU modules generate the unexpected noise with customer's application. If customer has problem SMU modules, send whole mainframe with SMU modules installed to nearest Agilent repair bench.

#### **SSU Bench Technician:**

Replace the failure SMU module with new PN of one.

After replace the SMU modules, perform the following calibration items.

- Assign the module parts number (See Service Note B1500A-02)
- Calibration for SMU range resistor
- Performance Verification: SMU voltage test, SMU current pre-test, SMU current test, and SMU CMR test For more detail about Performance Verification, please see Service Guide.