B2985B-01

Modification Recommended Service Note

Supersedes: NONE

B2985B Electrometer/High Resistance Meter, 0.01fA, 1000V

Serial Numbers:

See table below.

The Problem

The LAN MAC address assigned to B2985B may have a duplicate with the one assigned to 33502A.

Parts Required:

NONE

ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[[]] ON SPECIFIED FAILURE X AGREEABLE TIME	STANDARDS LABOR: 1.0 Hours
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE (active On-site contract required) X SERVICE CENTER [[]] CHANNEL PARTNERS	SERVICE: [[]] RETURN USED [[]] RETURN INVENTORY: [[]] SCRAP PARTS: [[]] SCRAP X SEE TEXT X SEE TEXT
AVAILABILITY: PRODUCT'S SUPPORT LIFE		NO CHARGE AVAILABLE UNTIL: Dec 31, 2022
[[]] Calibration Required X Calibration NOT Required		PRODUCT LINE: 1H AUTHOR: HT

ADDITIONAL INFORMATION:



Situation:

If B2985B is connected to the same LAN with 33502A, there may be a conflict and may cause issues related to LAN communication.

Solution/Action:

Send the B2985B to the Keysight Service Center for changing the LAN MAC address to a unique number that will not have the conflict with other equipment.

Affected Instruments:

The instruments with the serial numbers listed below are confirmed to be affected:

MY61080123	MY61100134
MY61080124	MY61100135
MY61080125	MY61100136
MY61080126	MY61100137
MY61080127	MY61100138
MY61080128	MY61100139
MY61080129	MY61100141
MY61080130	MY61100142
MY61080131	MY61100143
MY61080132	MY61100144
MY61080133	MY61100145
MY61080127 MY61080128 MY61080129 MY61080130 MY61080131 MY61080132	MY61100138 MY61100139 MY61100141 MY61100142 MY61100143 MY61100144

Revision History:

Date	Service Note Revision	Author	Reason for Change
10 Nov 2021	01	Hiro Tsunemoto	As Published