

DSO6104L-01-S

### Safety Service Note

Implemented During Normal Course of Providing Support

Supersedes: NONE

### DSO6104L Oscilloscope, LXI, 4-channel, 1 GHz

Serial Numbers: MY59450205

POSSIBLE "SHOCK" HAZARD

WARNING

HAZARD CLASS "3"

The Problem – A Foam Filled EMI Gasket was used in the units listed above. It was implemented in a total of 52 6000L units starting in Nov'2019 with SN: MY5945xxxx in response to a change in EMI qualification. It has been found that the Foam Filled EMI Gasket, if placed incorrectly, may not meet the safety creepage and clearance requirements and could cause a safety risk to the user.

### ADMINISTRATIVE INFORMATION

ACTION	[[]] ON SPECIFIED FAILURE	STANDARDS	
CATEGORY:	x AGREEABLE TIME	LABOR: 2.0 Hours	
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE (active On-site contract required) x SERVICE CENTER [[]] CHANNEL PARTNERS	SERVICE: [[]] RETURN USED INVENTORY: [[]] SCRAP PARTS: [[]] SEE TEXT	[[]] RETURN x SCRAP [[]] SEE TEXT
AVAILABILITY	: EOS	NO CHARGE AVAILABLE UNTIL: ALWAYS	
	x Calibration Required []] Calibration NOT Required	PRODUCT LINE: PL1A AUTHOR: JES	

ADDITIONAL INFORMATION:



### Parts Required:

P/N	Description	Qty.						
D6104-85405	Clip-on EMI Gasket Fingerstock, 3.47 inch length	1						
D6104-00104	Cover Assembly	1						


### Situation:

The current Foam Filled EMI Gasket (implemented in Nov 2019) in the 6000L series scopes was placed incorrectly and may not meet the safety creepage and clearance requirements and could a cause safety risk to the user, therefore the cover assembly and EMI Gasket need to be replaced. This is ONLY APPLICABLE FOR the units with the designated serial numbers which will be RECALLED back to SSU for repair.

# Current Foam Filled EMI Gasket Current Foam Filled EMI Gasket is attached onto the cover assembly.



# New Clip-on EMI Gasket New Clip-on EMI Gasket (D6104-85405) is manually inserted into the sheet metal divider of the chassis.



### Solution/Action:

Use the following steps to...

- replace the existing Cover Assembly with a new Cover Assembly without the foam EMI gasket
- and to apply a new clip-on EMI Gasket Fingerstock (D6104-00104) to the affected units.
- 1. Remove and scrap the original cover assembly (D6104-00104) with the foam EMI gasket from the scope.
  - Turn off the oscilloscope and disconnect the power cable.
  - Turn the oscilloscope so the bottom is facing up.
  - Using a T10 screwdriver, remove 5 screws from the rear and sides of the cabinet.
  - Slide the bottom cover back and up to remove.





Figure 13 Removing the cover


2. Prepare the Gasket Orientation Guide and 1pcs of the new Clip-on EMI Gasket Fingerstock (D6104-85405) as shown below:



Slot in the orientation



3. Slot in the Gasket Orientation Guide into the chassis as shown in the picture below:






4. Insert the Clip-on EMI Gasket Fingerstock (D6104-85405) into the sheet metal divider and press it with finger force until it is fully inserted as shown in pictures below.













Example of WRONG placement of EMI gasket Fingerstock as below:





5. Apply the new Cover Assembly (D6104-00104) WITHOUT an EMI gasket attached to it.



6. Follow the instructions in step 1 in reversion order to assemble the new Cover Assembly (D6104-00104) onto the 6000L Series unit and complete assembly of the unit.

### Note:

• If there are other repairs which are not stated in this Service Note, standard procedure will be applied for the other 6000L Series repairs.

### Revision History:

Date	Service Note Revision	Author	Reason for Change	
15 Oct 2020	01-S	Judith Smith	As Published	