DSO90604A-04

<u>SERVICE NOTE</u>

Supersedes: None

DSA/DSO 90000A Series Oscilloscopes

Serial Numbers: "ALL"

Some customers have noticed a slight crackling or buzzing sound coming from the rear of the instrument. This typically is in Europe where they operate the instrument with 240Volt @ 50Hz input power characteristics.

Parts Required:
P/NDescriptionQty.54913-68704Power supply subassembly1

ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICATION: | | | |
|--|---|--|---|
| MODIFICATION RECOMMENDED | | | |
| ACTION CATEGORY: | x ON SPECIFIED FAILURE [[]] AGREEABLE TIME | STANDARDS LABOR: 1.0 Hours | |
| LOCATION CATEGORY: | [[]] CUSTOMER INSTALLABLE [[]] ON-SITE x SERVICE CENTER [[]] CHANNEL PARTNER | SERVICE x RETURN INVENTORY: [[]] SCRAP [[]] SEE TEXT | USED X RETURN PARTS: [[]] SCRAP [[]] SEE TEXT |
| AVAILABILITY: | PRODUCT'S SUPPORT LIFE | NO CHARGE AVAILABLE UNTIL: (April 31,2011) | |
| AUTHOR: MR | | PRODUCT LINE: PL1A | |
| ADDITIONAL INFORMATION: Return Power Supply Agilent will receive credit. | | | |

© AGILENT TECHNOLOGIES, INC. 2009 PRINTED IN U.S.A.



April 13, 2009

Situation:

Some customers have noticed a slight crackling or buzzing sound coming from the rear of the instrument. This typically is in Europe where they operate the instrument with 240Volt @ 50Hz input power characteristics.

Solution/Action:

Review the manufacturing serial number on the power supply and if it first digit begins with a T,U then the power supply needs to be replaced. If the serial number begins with a V and the second digit is a A,B or C then the power supply needs to be replaced.

If the power supplies serial number is "VDxxxxx", than it is a power supply that has been modified and should not be exhibiting this issue.