

Modification Recommended Service Note

Supersedes: NONE

DSOS054A – DSO Infiniium S Series 500MHz 4 channel

Serial Numbers: MY58060101, MY58060102, MY58060105 to MY58060108, MY58060117

The Problem – A pair of resistors were placed in the wrong location on the VCO circuitry.

Parts Requi P/N	red:	Descript	ion			Qty.			
54911-69511	or 54911-69521	PCA – Acquisitior	n Board (Tes	ted)	1			
ADMINISTRA	TIVE INFORMATION								
ACTION CATEGORY:	[X] ON SPECIFIED FAILURE [[]] AGREEABLE TIME		STANDARDS LAE	OR:	4.0 Hours	6			
LOCATION CATEGORY:	 []] CUSTOMER INSTALLABLE []] ON-SITE (active On-site contract [X] SERVICE CENTER []] CHANNEL PARTNERS 	required)	SERVICE: INVENTORY:	[[]]	RETURN SCRAP SEE TEXT		USED PARTS:	[X] RETURN [[]] SCRAP [[]] SEE TEXT	
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		NO CHARGE A	AVAII	LABLE UN	TIL: Ju	une 2020		
	[X] Calibration Required [[]] Calibration NOT Required		PRODUCT LI AUTHOR: E		PL-1A				

ADDITIONAL INFORMATION:



Situation:

Two resistors were placed in the wrong position on the VCO circuitry, therefore the acquisition board will need to be replaced in these units even if no failures are found.

Solution/Action:

Replace the acquisition boards with the ones mentioned above only if they also have the acquisition board mentioned on the table below. Otherwise, assume that the acquisition board has already been replaced and do not proceed with this Service Note.

If the oscilloscope meets the requirements as stated on the paragraph above, then enter the serial number in Siebel. Here's a list of the faulty units along with their faulty acquisition boards.

Model	Scope S/N	Board S/N
DSOS054A	MY58060101	54911664010652320174500054
	MY58060102	54911664010652320173700096
	MY58060105	54911664010652320174000041
	MY58060106	54911664010652320174400045
	MY58060107	54911664010642320172700051
	MY58060108	54911664010652320174000015
	MY58060117	54911664010652320174000036

Revision History:	Service Note Author		Reason for Change		
	Revision		0		
07 Jun 2018	01	Ed Gorbea	As Published		