DSOS204A-04

Modification Recommended Service Note

Supersedes: NONE

DSOS204A - DSO Infiniium S Series 2GHz 4 channel

Serial Numbers: MY58060101, MY58060102, MY58060106, MY58060107, MY58060108

The Problem – A pair of resistors were placed in the wrong location on the VCO circuitry.

Parts Required:

P/N Description Qty.

54911-69511 or 54911-69521 PCA – Acquisition Board (Tested) 1

ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[X] ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 4.0 Hours
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE (active On-site contract required) [X] SERVICE CENTER [[]] CHANNEL PARTNERS	SERVICE: [X] RETURN USED [X] RETURN INVENTORY: [[]] SCRAP PARTS: [[]] SCRAP [[]] SEE TEXT [[]] SEE TEXT
AVAILABILITY	: PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: June 2020
	[X] Calibration Required [[]] Calibration NOT Required	PRODUCT LINE: PL-1A AUTHOR: EG

ADDITIONAL INFORMATION:



Situation:

Two resistors were placed in the wrong position on the VCO circuitry, therefore the acquisition board will need to be replaced in these units even if no failures are found.

Solution/Action:

Replace the acquisition boards with the ones mentioned above only if they also have the acquisition board mentioned on the table below. Otherwise, assume that the acquisition board has already been replaced and do not proceed with this Service Note.

If the oscilloscope meets the requirements as stated on the paragraph above, then enter the serial number if the acquisition board in Siebel. Here's a list of the faulty units along with their faulty acquisition boards.

Model	Scope S/N	Board S/N
DSOS204A	MY58060101	54911664010652320174000076
	MY58060102	54911664010652320174400118
	MY58060104	54911664010642320171100058
	MY58060106	54911664010652320174000034
	MY58060107	54911664010652320174500096
	MY58060108	54911664010652320173700112

Revision History:

Date	Service Note Revision	Author	Reason for Change	
07 Jun 2018	01	Ed Gorbea	As Published	