DSOS604A-05

# Modification Recommended Service Note

Supersedes: NONE

## DSOS604A - DSO Infiniium S Series 6GHz 4 channel

Serial Numbers: MY58060101to MY58060103, MY58060105, MY58060108, MY58060111.

The Problem – A pair of resistors were placed in the wrong location on the VCO circuitry.

Parts Required:

P/N Description Qty.

54911-69511 or 54911-69521 PCA – Acquisition Board (Tested) 1

ADMINISTRATIVE INFORMATION

ACTION CATEGORY:	[X] ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS LABOR: 4.0 Hours	
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE (active On-site contract required) [X] SERVICE CENTER [[]] CHANNEL PARTNERS	SERVICE: [X] RETURN USED [X] RETURI INVENTORY: [[]] SCRAP PARTS: [[]] SCRAP [[]] SEE TEXT	
AVAILABILITY	': PRODUCT'S SUPPORT LIFE	NO CHARGE AVAILABLE UNTIL: June 2020	
	[X] Calibration Required [[]] Calibration NOT Required	PRODUCT LINE: PL-1A AUTHOR: EG	

ADDITIONAL INFORMATION:



#### Situation:

Two resistors were placed in the wrong position on the VCO circuitry, therefore the acquisition board will need to be replaced in these units even if no failures are found.

#### Solution/Action:

Replace the acquisition boards with the ones mentioned above only if they also have the acquisition board mentioned on the table below. Otherwise, assume that the acquisition board has already been replaced and do not proceed with this Service Note.

If the oscilloscope meets the requirements as stated on the paragraph above, then enter the serial number if the acquisition board in Siebel. Here's a list of the faulty units along with their faulty acquisition boards.

Model	Scope S/N	Board S/N
DSOS604A	MY58060101	54911664010652320174400012
	MY58060102	54911664010652320174500112
	MY58060103	54911664010642320172300115
	MY58060105	54911664010732320180600038
	MY58060108	54911664010642320173100059
	MY58060111	54911664010652320174000050

### Revision History:

07 Jun 2018 01 Ed Gorbea As Published
27 Gail 2010