S E R V I C E N O T E

SUPERSEDES: NONE

E1401B 13-Slot, C-size VXI Mainframe

Serial Numbers: 0000A00000 / 9999Z99999

Some E1401B power supplies will not operate between 240 and 255 VAC when driving a light load (approximately 120 Watts).

To Be Performed By: Customer or Agilent-Qualified Personnel.

Parts Required:

P/N Description

Quantity

E1401-69203 RSTRD 0950-3704 (Exchange power supply assembly)

Situation:

The converter shutdown circuitry, in the E1401B power supply, has been picking up enough noise to have it's output oscillate when the bulk supply goes into an idle mode at high line and low load. The shutdown activation is causing the loss of one converter drive pulse causing the 5V to fall below minimum for approximately 800uSec. This activates the ACFail and System Reset logic signals giving false failure signals.

Continued

DATE: August 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: LABOR 0.5 Hours
LOCATION CATEGORY:	■ CUSTOMER INSTALLABLE■ ON-SITE■ SERVICE CENTER	SERVICE RETURN USED RETURN INVENTORY: SCRAP SEE TEXT SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: September 2001
AUTHOR: DMT	ENTITY: 0900	ADDITIONAL INFORMATION:

© 2000 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Page 2 Service Note E1401B-04

Solution / Action:

Replace the power supply with an updated exchange assembly. Updated power supplies can be identified by the manufacturer's revision code. Exchange power supplies (E1401-69203) with revision code "J" or greater have been modified to insure operation at high line voltages and low load conditions. Likewise, new supplies (0950-3704) with revision code of "J" or greater have been modified.