E1411B-02

S	Е	R	V	I	С	Е	Ν	0	Т	Е
							SUPERSEDE	ES: None)	
E14	411B 5	1/2 Dig	git Mu	ltime	ter (V)	KI C-siz	ze)			
Seri	al Numb	ers: 3002	2A00202	/ 3002	A00324					
	dification troller	-	revent l	osing	ı readir	ngs whe	en operating	with a '	V/360	
To F	Be Perfor	med By:	Agilent-	Qualif	ied Persc	onnel				
	t s Requi i per Wire	r ed: (22 gaug	e or equi	valent)						
If th		3 is instal atroller, it				•	h an embedded ionally.	V/360		
								(Continued	
							DATE: 1 June	991		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:							
	MODIFICATION	RECOMMENDED					
ACTION CATEGORY:	 IMMEDIATELY ON SPECIFIED FAILURE AGREEABLE TIME 	D FAILURE Labor 0.5 Hour					
LOCATION CATEGORY:	 CUSTOMER INSTALLABLE ON-SITE SERVICE CENTER 	SERVICE					
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: June 1993					
AUTHOR: KD	ENTITY: 0900	ADDITIONAL INFORMATION: Internal reference PCO 09-28462					

© 1991 AGILENT TECHNOLOGIES
PRINTED IN U.S.A.



Solution/Action:

To prevent the above condition from causing a problem with lost readings, proceed as follows:

CAUTION:

The E1411B contains static-sensitive devices. Use an approved ESD safe workstation for this modification!

- 1. Remove the E1411B top shield (7 screws, Torx T10).
- 2. On the component side of PC assembly E1411-66511, cut the trace going to pin 6 of U2.
- 3. Using a jumper wire, connect pin 4 of U2 to pin 15 of U29.
- 4. Reassemble the E1411B.