S E R V I C E N O T E

SUPERSEDES: NONE

6-Slot, C-size VXI Mainframe

Serial Numbers: 0000A00000 / 9999Z99999

The power supply will not operate at 90-Volt, 50Hz AC power.

To Be Performed By: Customer or Agilent-Qualified Personnel.

Parts Required:

P/NDescriptionQuantityE1401-69202RSTRD 0950-2283 (Exchange power supply assembly)1

Situation:

Some E1421B power supplies, when connected to a low input voltage, are asserting the AC_FAIL signal. When the AC_FAIL signal is true, the SYSRST signal on the slot 0 controller is asserted. This in turn sets the SYS_FAIL signal true.

Solution / Action:

Replace the power supply with an updated exchange assembly. Updated power supplies can be identified by the manufacturer's revision code. Exchange power supplies (E1401-69202) with revision code **/AY or greater have been modified to insure operation at line voltages as low as 90VAC (** is the original revision code). Likewise, new supplies (0950-2283) with revision codes of AY or AY-1 or greater have been modified.

DATE: May 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:				
MODIFICATION RECOMMENDED				
ACTION CATEGORY:	☐ IMMEDIATELY ☐ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: LABOR 0.5 Hours		
LOCATION CATEGORY:	■ CUSTOMER INSTALLABLE □ ON-SITE ■ SERVICE CENTER	SERVICE INVENTORY:	RETURN SCRAP SEE TEXT	USED RETURN PARTS: SCRAP SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: May 2001		
AUTHOR: DMT	ENTITY: 0900	ADDITIONAL INFORMATION:		

© 1999 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

