S E R V I C E N O T E

SUPERSEDES: E3612A-01 dated

26 August 1993

3612A 30W Lab Bench DC Power Supply

E3610A-04 Serial Numbers: 3111K00101 / 3151K02863

KR22702864 / KR30704551

E3611A-05 Serial Numbers: 3111K00101 / 3151K02184

KR22102185 / KR30704381

E3612A-03 Serial Numbers: KR15300101 / KR30701277

Duplicate Service Notes:

E3610A-04 E3611A-05 E3612A-03

Eliminate voltage transient above the output setting during turn-off

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

Part No. Qty. Description

0180-4355 1 Capacitor, 470uF 50V

Continued

DATE: January 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	☐ IMMEDIATELY ■ ON SPECIFIED FAILURE ☐ AGREEABLE TIME	STANDARDS: Labor 0.5 Hour
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE RETURN USED RETURN INVENTORY: SCRAP PARTS: SCRAP SEE TEXT SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: February 1996
AUTHOR: NKP	ENTITY: Y300	ADDITIONAL INFORMATION: Reissued to extend no charge period

© 1996 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Situation:

Some of the power supplies have turn-off overshoot that exceeds the power supply output setting. If this condition exists it will occur when the power supply has a light load (output current less than 30 mA).

Solution/Action:

To determine if a particular power supply has "excess turn-off overshoot" follow this test sequence:

- 1. Connect the power supply to the ac power line.
- 2. Turn the power supply "on".
- 3. Connect a DVM across the power supply output terminals (set the DVM to continuously sample, rate should should be at least two samples per second).
- 4. Set the power supply output voltage to any value below half scale (no load condition).
- 5. Observe the DVM readings of the power supply output when the supply is switched to "off".
- 6. If the readings increase after the power supply is switched "off" by more than 5% then the power supply has "excess turn-off overshoot".

"Excess turn-off overshoot" may be corrected by replacing C13 (P/N 01810-4085) with P/N 0180-4355 (470 uF 50V).