S E R V I C E N O T E

SUPERSEDES: NONE

E3634A DC Power Supply

Serial Numbers: See below.

Duplicate Service Notes: E3633A-02: KR82600051/KR92800741

E3634A-02: KR84900051/KR92900529

Over Current Protection (OCP) is not functional

To Be Performed By:

Agilent-Qualified Personnel

Parts Required:

P/N	Description	Quantity	
E3633-60034	Programmed ROM	1	
E3634-60034	Programmed ROM	1	

Situation:

1. If the value of resistive load is less than 0.4 ohm when the OCP crcuit is tripped, a pulse current occurs in the output terminal. The pulse width is 10 msec, period is 30 sec and amplitude is the value of current limit setting.

Continued

DATE: November 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

MODIFICATION RECOMMENDED

ACTION CATEGORY:	IMMEDIATELY ON SPECIFIED FAILURE AGREEABLE TIME	STANDARDS: LABOR 0.5 Hours			
LOCATION CATEGORY:	CUSTOMER INSTALLABLE ON-SITE SERVICE CENTER	SERVICE INVENTORY:	RETURN SCRAP SEE TEXT	USED PARTS:	RETURN SCRAP SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: November 2002			
AUTHOR: NKP	ENTITY: MR00	ADDITIONAL INFORMATION:			

© 1999 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Page 2 Service Note E3634A-02

2. If the value of resistive load is greater than 0.4 ohm when the OCP crcuit is tripped, the output voltage is 1 V and the output current is set by the Ohm's law.

- 3. If clearing the OCP condition when setting the OCP trip level to 0.2 A, OCP function is not operational.
- 4. When setting the OCP trip level to 0.2 A, OCP function is not operational intermittently.

Solution / Action:

- 1. Replace the programmed ROM with REV. 1.4. The part numbers are E3633-60034 for the E3633A power supply and E3634-60034 for the E3634A power supply
- 2. Note that you have to recalibrate the power supply after changing the programmed ROM.