E3647A-03 <u>S E R V I C E N O T E</u>

Supersedes: NONE

E3647A DC Power Supply

Serial Numbers: MY40001945 / MY40002200

Difficulty to adjust the knob control on front panel due to encoder issue.

To Be Performed By: Agilent-Qualified Personnel

Parts Required:
P/NDescriptionQty.0960-2545Rotary encoder insulated shaft1

ADMINISTRATIVE INFORMATION

| SERVICE NOTE CLASSIFICATION: | | | |
|--|---|--|---|
| MODIFICATION RECOMMENDED | | | |
| ACTION CATEGORY: | [[]] IMMEDIATELY X ON SPECIFIED FAILURE [[]] AGREEABLE TIME | STANDARDS: LABOR: 0.5 Hours | |
| LOCATION CATEGORY: | [[]] CUSTOMER INSTALLABLE [[]] ON-SITE X SERVICE CENTER | SERVICE [[]] RETURN INVENTORY: [[]] SCRAP X SEE TEXT | USED [[]] RETURN PARTS: [[]] SCRAP X SEE TEXT |
| AVAILABILITY: | PRODUCT'S SUPPORT LIFE | AGILENT RESPONSIBLE UNTIL: February 2009 | |
| AUTHOR: CH | PRODUCT LINE: WC | | |
| ADDITIONAL INFORMATION: | | | |
| © AGILENT TECHNOLOGIES, INC. 2007 PRINTED IN U.S.A. | | | |

February 14, 2007



Situation:

- 1) When turning the knob of the power supply, user will find it difficult to adjust to get the desired setting (example of difficulty user need a few turns to increase just a step of voltage/current).
- 2) Some times, by turning the knob clockwise to increase the voltage and current setting, user will see a decrease in values.

Solution/Action:

- 1) If the unit is confirmed having the problem described above (after verification steps), continue with Step 2. Otherwise, no further action is required.
- 2) Remove encoder (reference designator RE1) on the front panel display PCA. Replace with another encoder (refer to Picture 1 below).

