									E44	102B-	04
S	Е	R	V		С	Е		Ν	0	Т	Ε
										. .	
T 4 4	0 1 D T		T 4 4 0	an			SUPERS	SEDE	S: NOP	NE	
		E4402B	/								
	,	E4405B	,	7 B ,							
	,	nd E44									
ESA	Spec	trum A	Analyz	er fan	nily.						
Also											
E74	01A, I	E 7402 A	A, E74 0)3A,							
		nd E7	/								
		-Comp		Analy	7ers						
		- F		J							
Seria	l Numb	ers/Dup	licate Se	rvice N	otes: See	Below					
unde	er cert	ain env	vironme	ental c	onditio	ons, whi	ch can	ultima	ately s	endrites hort out	
		•		•	•	on the a	nalyzer	not to	o funct	ion.	
	-	ım Analy									
		US3901				No Exce		41057			
		US3901 US3901				No Exception	ons: S394	41057			
		US3901				Exception					
2110	ID 051	0.000001	01017 0	557110			0526, US	394405	527. USE	39440528	
E440	5B-03:	US3901	0101 / U	S39440	354	No Exce			,		
E440'	7B-03:	US3901	0101 / U	S39440	941	No Exce	eptions.				
		US3901					ons: US39	944036	7		
E441	1 B- 04:	US3901	0101 / U	S39441	107	No Exce	eptions.			Continue	d
							DATE: N	May 20	000		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLAS	SSIFICATION:					
MODIFICATION RECOMMENDED						
ACTION CATEGORY:	IMMEDIATELY ON SPECIFIED FAILURE AGREEABLE TIME	STANDARDS: LABOR 1.0 Hours				
LOCATION CATEGORY:	CUSTOMER INSTALLABLE ON-SITE SERVICE CENTER	SERVICE □ RETURN USED □ RETURN INVENTORY: ■ SCRAP PARTS: ■ SCRAP □ SEE TEXT □ SEE TEXT □ SEE TEXT				
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: End of GMS period				
AUTHOR: BD	ENTITY: 5320	ADDITIONAL INFORMATION:				

© 2000 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Agilent Technologies

EMC Pre-Compliance Analyzer Serial Numbers:

E7401A-03:	US39110101 / US39440310
E7402A-03:	US39110101 / US39440175
E7403A-03:	US39110101 / US39440132
E7404A-03:	US39110101 / US39440120
E7405A-03:	US39110101 / US39440174

To Be Performed By: Agilent Service Centers Only

Parts Required:

P/N	Description	Quantity

E4401-60198 Flex Circuit 1

Situation:

The front panel flex circuits that are green in color can grow dendrites, which can ultimately short out traces causing the front panel keys not to function. The "green" circuits utilize silver which can cause this dendrite growth. The new "copper" colored flex circuits utilize copper/nickel/gold plating which performs very well under various environmental conditions.

Solution / Action:

Agilent Service Centers should replace the flex circuits if the instrument serial falls within the specified range. Another method would be to look at the color of the existing flex circuit. All green flex circuits are suspect and should be replaced. Service Center personnel should refer to the ESA Service Guide for proper installation of the flex circuit.