# S E R V I C E N O T E

SUPERSEDES: NONE

# ESA Spectrum Analyzer family.with option UKB

# **Serial Numbers:**

E4402B US39010101 / US99999999 (Option UKB only)

E4404B US39010101 / US99999999

E4405B US39010101 / US99999999

E4407B US39010101 / US99999999 (Option UKB only)

Instruments within this serial range that have firmware revision less than or equal to A.05.00 will fail frequency response performance tests, AC coupled, at 100 kHz center frequency

# **Duplicate Service Notes:**

E4402B-09

E4404B-08

E4405B-08

E4407B-08

To Be Performed By: Agilent Service Centers Only

Continued

DATE: November 2001

# **ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	<ul><li>■ IMMEDIATELY</li><li>□ ON SPECIFIED FAILURE</li><li>□ AGREEABLE TIME</li></ul>	STANDARDS: LABOR 1.0 Hours
LOCATION CATEGORY:	☐ CUSTOMER INSTALLABLE☐ ON-SITE☐ SERVICE CENTER	SERVICE RETURN USED RETURN PARTS: SCRAP SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: End of GMS period
AUTHOR: BD	ENTITY: 5320	ADDITIONAL INFORMATION:

© 2001 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



# Parts Required:

Firmware upgrade which can be obtained three different ways:

- 1) Order as an E440XBU option UE2 or E740XBU option UE2
- 2) Download latest instrument firmware from the customer viewable website at: http://www.agilent.com/find/esa or http://www.agilent.com/find/emc
- 3) Download the latest instrument firmware from our internal service website at: http://mktwww.soco.agilent.com/field/service/signal/esa/firmware

# **Situation:**

Firmware versions less than or equal to A.05.00 do not apply the frequency response corrections while in AC coupled mode.

#### **Solution / Action:**

Upgrade the instrument firmware in order to get the test to pass.