E4438C-01

S E R V I C E N O T E

Supersedes: NONE

E4438C Vector Signal Generator with Option UN7

Serial Numbers: US0000000/US41460775 and MY0000000/MY42080122

Replace A11 BER Board Assembly to correct Clock/Gate Delay

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

P/N Description Qty.

E4400-60519 A11 BER Board Assembly 1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	[[]] IMMEDIATELY X ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS: LABOR: 1.0 Hours
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE X SERVICE CENTER	SERVICE X RETURN USED [[]] RETURN INVENTORY: [[]] SCRAP PARTS: X SCRAP [[]] SEE TEXT [[]] SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: Warranty Period
AUTHOR: FD	PRODUCT LINE: 15	
ADDITIONAL INFORMATION:		

© AGILENT TECHNOLOGIES, INC. 2002 PRINTED IN U.S.A.



Page 2 of 2 E4438C-01

Situation:

The customer encounters difficulties using the Baseband BERT measurement with the Clock or Gate Delay adjustment activated. The symptoms reported include a combination of the following: 1) the BER measurement is "unstable" and appears inaccurate; 2) synchronization with the data signal is difficult; 3) the delay value appears inaccurate.

Solution/Action:

Use the Installed Board Info screen of the signal generator to confirm that the installed BERT board (E4400-60519) has version A0100. If this is the case, replace the board. Refer to the Service Guide for the replacement procedure. Upon installation of the new board, verify that the version of the board is now A0110.