E5061A-08B SERVICE NOTE

Supersedes: E5061A-08A

E5061A ENA Series Network Analyzer, 300kHz to 1.5GHz

Serial Numbers: MY44100001 to MY44206760, SG44100001 to SG44200504

Source level might decrease gradually and become out of spec.

Parts Required:

P/N Description Qty.

N/A

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION AVAILABLE			
ACTION CATEGORY:: AGREEABLE TIME	[[]] PERFORMANCE ENHANCEMENT [X] SERVICE / RELIABILITY ENHANCEMENT		
LOCATION [[]] CUSTOMER INSTALLABLE CATEGORY: [[]] ON-SITE (active On-site contract required) [X] SERVICE CENTER [[]] CHANNEL PARTNERS	AVAILABILITY: Until End of Support		
[X] Calibration Required [[]] Calibration NOT Required	PRODUCT LINE: WN AUTHOR: jm		
ADDITIONAL INFORMATION:			

© AGILENT TECHNOLOGIES, INC. 2013 PRINTED IN U.S.A.



Page 1 of 2

June 20, 2013
Rev. 21

Page 2 of 2 E5061A-08B

Situation:

Source level might decrease gradually and become out of spec.

It might occur whether customer turn on a unit or not.

Solution/Action:

- 1. Perform the following adjustments by using E5061A/ E5062A Adjustment Program Version A.02.00 or later.
 - ✓ Synthesizer Gain Adjustment
 - ✓ Local Output Power Adjustment
 - ✓ Source Output Power Adjustment
 - ✓ Receiver IF Range Adjustment
 - ✓ Receiver Ports Characteristics Adjustment
- 2. Perform the verification tests.
 - ✓ "To execute the Diagnostic Test" on Chapter 4 → Troubleshooting →

 "Troubleshooting Using Diagnostic Test" on E5061/ E5062A service manual.
 - ✓ Frequency Accuracy Test
 - ✓ RF Output Level Accuracy and Flatness Test
 - ✓ RF Output Level Linearity Test
 - ✓ Trace Noise Test
 - ✓ Crosstalk & System Dynamic Range Test
 - ✓ Dynamic Accuracy Test
 - ✓ Uncorrected System Performance Test
- 3. If there is a FAIL test, replace A1 Source Board.

If there is no FAIL test, verification is done correctly.

Revision History:

	Revision	Date	Author	Reason For Change	
	Number				
	1.0	Oct 2009	jm	As published	
ĺ	1.1	Mar 2011	jm		
	1.2	June 2013	ls	Add availability date	