

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

E5091A-03

S E R V I C E N O T E

Supersedes:
None

Agilent E5091A Multiport Test Set

Serial Numbers: [0000A00000 / 9999Z99999]

SW2 Coaxial Switch part number change

Parts Required:

P/N	Description	Qty.
5087-7272	Enhanced Tsunami switch	1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY
AUTHOR: DK PRODUCT LINE: WN
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2003
PRINTED IN U.S.A.



December 1, 2003

Situation:

The coaxial switch that is used for SW2 of the E5091A was changed from 5087-7137 to 5087-7272 to improve an input voltage tolerance. Switches parts were used as follows:

***Option 009 (9 ports option)**

Serial number MY42100110 and below, and all JP1KJXXXXX

P/N	Description	Qty.
5087-7137	9 GHz SWITCH	7 for SW1 to SW7

Serial number MY42100111 and later

P/N	Description	Qty.
5087-7137	9 GHz SWITCH	6 for SW1, and SW3 to SW7
5087-7272	Enhanced Tsunami switch	1 for SW2

***Option 007 (7 ports option)**

Serial number MY42100110 and below, and all JP1KJXXXXX

P/N	Description	Qty.
5087-7137	9 GHz SWITCH	5 for SW1 to SW5


Serial number MY42100111 and later

P/N	Description	Qty.
5087-7137	9 GHz SWITCH	4 for SW1, and SW3 to SW5
5087-7272	Enhanced Tsunami switch	1 for SW2


Solution/Action:

Use a newer part 5087-7272 when replacing SW2. Refer to following figures about the SW2 position.

Opt. 009



Opt. 007



Retrofit Time

Assembly Time: No additional time due to this service note.

Adjustment Time: No additional time due to this service note.

Performance Tests Time: No additional time due to this service note.

Total Time: No additional time due to this service note.