E5091A-04

<u>SERVICE NOTE</u>

Supersedes: None

Agilent E5091A Multiport Test Set

Serial Numbers: [MY42100363 – MY42100530]

Specified Option: E5091A-016

Voltage output of Control Line Pin-12 cannot be output due to A3 failure

Parts Required:

P/N Description Qty.

E5091-66503 A3 DUT CONTROL BOARD 1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION RECOMMENDED		
ACTION CATEGORY:	[[]] IMMEDIATELY X ON SPECIFIED FAILURE [[]] AGREEABLE TIME	STANDARDS: LABOR: 0.5 Hours
LOCATION CATEGORY:	[[]] CUSTOMER INSTALLABLE [[]] ON-SITE X SERVICE CENTER	SERVICE [[]] RETURN USED [[]] RETURN INVENTORY: X SCRAP PARTS: X SCRAP [[]] SEE TEXT [[]] SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: Feb 2009
AUTHOR: jm PRODUCT LINE: WN		
ADDITIONAL INFORMATION:		

© AGILENT TECHNOLOGIES, INC. 2007 PRINTED IN U.S.A.



Page 2 of 2 E5091A-04

Situation:

If we rotate the voltage adjustment trimmer on the front panel, the voltage output of control line Pin-12 on the front panel must be varied from +2V to +5V.

Some units among the indicated serials and specified option cannot output the voltage. It is almost around zero volts.

This failure is occurred for Option E5091A-016 only.

Solution/Action:

If the failure occurred, replace A3 DUT CONTROL BOARD.

Procedure:

- 1) Refer to "Check the voltage output of the Control Lines" at "Troubleshooting" section in the service guide (E5091-90110, p126), and confirm the failure is occurred.
- 2) If output voltage is incorrect, replace A3 DUT CONTROL BOARD (Service Guide, E5091-90110, p206).
- 3) Refer to "Check the voltage output of the Control Lines" and "Check control lines setting" in the service guide (E5091-90110, p126), and confirm it works correctly.

Retrofit Time:

Assembly Time: 15 minutes Adjustment Time: None.

Performance Tests Time: 15 minutes.

Total Time: 30 minutes.