

S E R V I C E N O T E

SUPERSEDES: NONE

**Agilent E5250A Low Leakage Switch Mainframe**

Serial Numbers: JP10C00540/JP10C00590

**Overstressed power supply transistor causes the E5250A to not turn on.**

**To Be Performed By:** Agilent-Qualified Personnel

**Parts Required:**

Agilent P/N	Description	Quantity
E5250-61001	Power Supply Unit	1

**Situation:**

The transistor on the power supply unit is not firmly attached to the heat sink. Therefore, the transistor may be damaged because of overheating. This will cause the E5250A to not turn on.

**Solution / Action:**

Replace the power supply unit (E5250-61001).

DATE: March 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 0.5 Hours
LOCATION CATEGORY:	<input type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
		USED PARTS:	<input type="checkbox"/> RETURN <input checked="" type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: March 2002	
AUTHOR: SY	ENTITY: 3300	ADDITIONAL INFORMATION:	

